
SIEMENS

SIMOVERT MASTERDRIVES Motion Control

Betriebsanleitung Operating Instructions

Wechselrichter (DC-AC) Bauform Kompakt PLUS Frequency Inverter (DC-AC) Compact PLUS Type



Ausgabe / Edition: AC

Bestell-Nr. / Order No.: 6SE7087-6KP50

Diese Betriebsanleitung gilt für den Gerätesoftwarestand V 1.2.

Änderungen von Funktionen, technischen Daten, Normen, Zeichnungen und Parametern vorbehalten.

These Operating Instructions are valid for software release V 1.2.

We reserve the right to make changes to functions, technical data, standards, drawings and parameters

Weitergabe sowie Vervielfältigung dieser Unterlage, Verwertung und Mitteilung ihres Inhalts nicht gestattet, soweit nicht ausdrücklich zugestanden. Zuwiderhandlungen verpflichten zu Schadenersatz. Alle Rechte vorbehalten, insbesondere für den Fall der Patenterteilung oder GM-Eintragung.

Wir haben den Inhalt der Druckschrift auf Übereinstimmung mit der beschriebenen Hard- und Software überprüft. Dennoch können Abweichungen nicht ausgeschlossen werden, so daß wir für die vollständige Übereinstimmung keine Garantie übernehmen. Die Angaben in dieser Druckschrift werden jedoch regelmäßig überprüft und notwendige Korrekturen sind in den nachfolgenden Auflagen enthalten. Für Verbesserungsvorschläge sind wir dankbar

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

We have checked the contents of this document to ensure that they coincide with the described hardware and software. However, differences cannot be completely excluded, so that we do not accept any guarantee for complete conformance. However, the information in this document is regularly checked and necessary corrections will be included in subsequent editions. We are grateful for any recommendations for improvement.

SIMOVERT® ist ein Warenzeichen von Siemens

SIMOVERT® Registered Trade Mark

Contents

1	DEFINITIONS AND WARNINGS1-1			
2	DESCRIPTION		2-1	
3	FIRST START-UP	4,	3-1	
4	TRANSPORT, STORAGE, UNPA	CKING	4-1	
	alor.			
5	INSTALLATION		5-1	
5.1	Installing the units			
5.2	Installing the optional boards	79 b	5-4	
5.2.1	Installing optional boards on units			
5.2.2	Installing optional boards on units	with a width of 135 mm	and 180 mm5-7	
6	INSTALLATION IN CONFORMAI	NCE WITH EMC REGU	LATIONS6-1	
7	CONNECTING-UP		7-1	
7.1	Power connections	West,	7-4	
7.1.1	Power connections for units with a	a width up to 90 mm	7-5	
7.1.2	Power connections for units with a			
7.2	Control connections	1/2	7-7	
8	PARAMETERIZATION			
8.1	Parameter input via the PMU	Willey.	8-2	
8.2	Parameter input via the OP1S		8-5	
8.3	Parameter reset to factory setting.		8-9	
8.4	Parameterizing by download		8-10	
8.5	Parameterizing with parameter mo	odules	8-11	
8.6	Complete parameterization		8-27	

9 1	MAINTENANCE			9-1
9.1	Replacing the fan	Trans.		9-2
9.1.1	Replacing the fan in units up	to 90 mm wide		9-2
9.1.2	Replacing the fan in units 13			
9.1.3	Replacing the fan in units up	to 180 mm wide		9-3
	Tales.			
10	FORMING	208	700	10-1
77.50	,	297	.4/0	
11	TECHNICAL DATA			11-1
4	8	8		8
12	FAULTS AND ALARMS	79,00	J. S.	12-1
	W	10°	10	
12.1	Faults			12-1
12.1	y adio	77.0	.W.O.	12 1
12.2	Alarms			12-11
12.2	/ (ICITIO			12 11
12.3	Fatal errors (FF)			12-31
12.0	Tatal Citors (FT)	X2X	\	12 01
13	ENVIRONMENTAL FRIEND	INESS		13-1
	LIVINGIMIENTALTRIEND	LII4L00	~87	15-1
14	CERTIFICATES			14-1
1_	OFILLIOUS FORMATION			I - I

1 Definitions and Warnings

Qualified personnel

For the purpose of this documentation and the product warning labels, a "Qualified person" is someone who is familiar with the installation, mounting, start-up, operation and maintenance of the product. He or she must have the following qualifications:

- Trained or authorized to energize, de-energize, ground and tag circuits and equipment in accordance with established safety procedures.
- Trained or authorized in the proper care and use of protective equipment in accordance with established safety procedures.
- Trained in rendering first aid.

DANGER



For the purpose of this documentation and the product warning labels, "Danger" indicates death, severe personal injury or substantial property damage will result if proper precautions are not taken.

WARNING



For the purpose of this documentation and the product warning labels, "Warning" indicates death, severe personal injury or property damage can result if proper precautions are not taken.

CAUTION



For the purpose of this documentation and the product warning labels, "Caution" indicates that minor personal injury or material damage can result if proper precautions are not taken.

NOTE

For the purpose of this documentation, "Note" indicates important information about the product or about the respective part of the documentation which is essential to highlight.

WARNING



Hazardous voltages are present in this electrical equipment during operation.

Non-observance of the warnings can thus result in severe personal injury or property damage.

Only qualified personnel should work on or around the equipment

This personnel must be thoroughly familiar with all warning and maintenance procedures contained in this documentation.

The successful and safe operation of this equipment is dependent on correct transport, proper storage and installation as well as careful operation and maintenance.

NOTE

This documentation does not purport to cover all details on all types of the product, nor to provide for every possible contingency to be met in connection with installation, operation or maintenance.

Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes, the matter should be referred to the local SIEMENS sales office.

The contents of this documentation shall not become part of or modify any prior or existing agreement, commitment or relationship. The sales contract contains the entire obligation of SIEMENS AG. The warranty contained in the contract between the parties is the sole warranty of SIEMENS AG. Any statements contained herein do not create new warranties or modify the existing warranty.

10.98 Definitions and Warnings

CAUTION



Components which can be destroyed by electrostatic discharge (ESD)

The board contains components which can be destroyed by electrostatic discharge. These components can be easily destroyed if not carefully handled. If you have to handle electronic boards, please observe the following:

Electronic boards should only be touched when absolutely necessary.

The human body must be electrically discharged before touching an electronic board.

Boards must not come into contact with highly insulating materials - e.g. plastic parts, insulated desktops, articles of clothing manufactured from man-made fibers.


Boards must only be placed on conductive surfaces.


Boards and components should only be stored and transported in conductive packaging (e.g. metalized plastic boxes or metal containers).

If the packing material is not conductive, the boards must be wrapped with a conductive packaging material, e.g. conductive foam rubber or household aluminium foil.

The necessary ESD protective measures are clearly shown again in the following diagram:

- ♦ a = Conductive floor surface
- ♦ b = ESD table
- ♦ c = ESD shoes
- ♦ d = ESD overall
- ♦ e = ESD chain
- ♦ f = Cubicle ground connection








Fig. 1-1 ESD proted

ESD protective measures



Safety and Operating Instructions for Drive Converters

(in conformity with the low-voltage directive 73/23/EEC)

1. General

In operation, drive converters, depending on their degree of protection, may have live, uninsulated, and possibly also moving or rotating parts, as well as hot surfaces.

In case of inadmissible removal of the required covers, of improper use, wrong installation or maloperation, there is the danger of serious personal injury and damage to property.

For further information, see documentation.

All operations serving transport, installation and commissioning as well as maintenance are to be carried out **by skilled technical personnel** (observe IEC 364 or CENELEC HD 384 or DIN VDE 0100 and IEC Report 664 or DIN VDE 0110 and national accident prevention rules).

For the purposes of these basic safety instructions, "skilled technical personnel" means persons who are familiar with the installation, mounting, commissioning and operation of the product and have the qualifications needed for the performance of their functions.

2. Intended use

Drive converters are components designed for inclusion in electrical installations or machinery.

In case of installation in machinery, commissioning of the drive converter (i.e. the starting of normal operation) is prohibited until the machinery has been proved to conform to the provisions of the EC directive 89/392/EEC (Machinery Safety Directive - MSD). Account is to be taken of EN 60204.

Commissioning (i.e. the start of normal operation) is admissible only where conformity with the EMC directive (89/336/EEC) has been established.

The drive converters meet the requirements of the low-voltage directive 73/23/EEC. They are subject to the harmonized standards of the series prEN 50178/DIN VDE 0160 in conjunction with EN 60439-1/DIN VDE 0660 Part 500 and EN 60146/DIN VDE 0558.

The technical data as well as information concerning the supply conditions shall be taken from the rating plate and from the documentation and shall be strictly observed.

3. Transport, storage

The instructions for transport, storage and proper use shall be complied with.

The climatic conditions shall be in conformity with prEN 50178.

4. Installation

The installation and cooling of the appliances shall be in accordance with the specifications in the pertinent documentation.

The drive converters shall be protected against excessive strains. In particular, no components must be bent and/or isolating distances altered in the course of transportation or handling. No contact shall be made with electronic components and contacts.

Drive converters contain electrostatic sensitive components which are liable to damage through improper use. Electronic components must not be mechanically damaged or destroyed (potential health risks)

5. Electrical connection

When working on live drive converters, the applicable national accident prevention rules (e.g. VBG 4) must be complied with.

The electrical installation shall be carried out in accordance with the relevant requirements (e.g. cross-sectional areas of conductors, fusing, PE connection). For further information, see documentation.

Instructions for the installation in accordance with EMC requirements, such as screening, grounding, location of filters and wiring, are contained in the drive converter documentation. They must always be complied with, also for drive converters bearing a CE marking. Observance of the limit values required by the EMC law is the responsibility of the manufacturer of the installation or machine.

6. Operation

Installations which include drive converters shall be equipped with additional monitoring and protective devices in accordance with the relevant applicable safety requirements, e.g. Act respecting technical equipment, accident prevention rules, etc. Changes to the drive converters by means of the operating software are permissible.

After disconnection of the drive converters from the voltage supply, live appliance parts and power terminals must not be touched immediately because of possibly energized capacitors. In this regard, the corresponding signs and markings on the drive converter must be respected.

During operation, all covers and doors shall be kept closed.

7. Maintenance and servicing

The manufacturer's documentation shall be followed.

Keep these safety instructions in a safe place!

10.98 Description

2 Description

Range of application

The inverter is a power electronics component for feeding highly dynamic three-phase drives in the output range from 0.75 kW to 18.5 kW.

The unit can be operated from a DC system with voltages from 510 V to 650 V.

The inverter enables a three-phase system with a variable output frequency between 0 Hz and 400 Hz to be generated from the DC link voltage with the pulse width modulation method (PWM).

The unit is controlled by the internal closed-loop control electronics which consists of a microprocessor and a digital signal processor (DSP). The functions are provided by the unit software.

The unit can be operated via the PMU operator control panel, the user-friendly OP1S operator control panel, the terminal strip or via the bus system. For this purpose, the unit has a number of interfaces and three slots for the use of optional boards.

Resolvers, encoders, pulse encoders and multiturn encoders can be used as encoders on the motor.




Fig. 2-1 Circuit principle of the inverter

10.98 First Start-up

First Start-up

Unpack and check the units

Mount the unit and install optional boards which have not yet been fitted



Form the DC link capacitors, if necessary

After removing the packaging, check that the unit is intact and undamaged. Only intact units may be started up. Please also check that the unit is complete, that the correct optional boards are fitted, and that the technology option has been released, if ordered.

Retrofit any optional boards which have not yet been installed, if necessary. Then install the units taking into account the requirements at the point of installation and the EMC instructions.

If the DC link of the unit was de-energized for more than

one year, you have to newly form the DC link capacitors

See section "Transport, Storage, Unpacking"

See section "Installation' and "Installation in Conformance with EMC Regulations"

> See section "Forming"

> See section

"Connecting-up"

and

"Installation in

Conformance

with EMC

Regulations'

Connect the protective conductor, the power cables or buses and, if present, the ext. 24 V supply



Power up the external 24 V supply or the line voltage



If necessary, carry out parameter reset to factory setting



Parameterizing by download or with parameter modules



Connect the control cables, communication cables, encoder cables and motor cables



Please connect, starting with the protective conductor, the power cables or DC link buses and, if present, the external 24 V supply. Pay attention to EMC instructions when laying the cables. Please do not at this stage connect any control, communication, encoder and motor cables (exception: cable for connecting up an OP1S, if parameterization is to be effected via the OP1S).

After checking that the cabling has been correctly connected and that it sits properly, power up the external 24 V supply or the line voltage. After the electronics power supply has been started, the unit initializes itself. The action can take several seconds. The drive status is subsequently shown on the PMU.

If the PMU does not show status °005 after completion of the unit initialization, or if the unit has already been parameterized before, you should carry out a parameter "Parameterization" reset to factory setting.

See section

See section "Parameterization'

Please connect the remaining control, communication, encoder and motor cables. Pay attention to the EMC instructions when laying the cables.

See section "Connecting-up" and "Installation in Conformance with EMC Regulations



After checking the unit and the cabling once more, power up the line voltage or DC bus voltage, if you have not already done so, and perform a function test according to your parameterization.

WARNING



It must be ensured that no danger for persons and equipment can occur by energizing the power and the unit. It is recommended not to couple the driven machine until the function test has been successfully completed.

Further start-up and parameterization according to your specific requirements

4 Transport, Storage, Unpacking

The units and components are packed in the manufacturing plant corresponding to that specified when ordered. A packing label is located on the outside of the packaging. Please observe the instructions on the packaging for transport, storage and professional

handling.

Transport Vibrations and jolts must be avoided during transport. If the unit is

damaged, you must inform your shipping company immediately.

Storage The units and components must be stored in clean, dry rooms.

Temperatures between -25 °C (-13 °F) and +70 °C (158 °F) are permissible. Temperature fluctuations must not be more than 30 K per

hour.

NOTE If the storage period of one year is exceeded, the unit must be newly

formed. See Section "Forming".

Unpacking The packaging comprises board and corrugated paper. It can be

disposed of corresponding to the appropriate local regulations for the disposal of board products. The units and components can be installed and commissioned after they have been unpacked and checked to ensure that everything is complete and that they are not damaged.

5 Installation

5.1 Installing the units

WARNING



Safe converter operation requires that the equipment is mounted and commissioned by qualified personnel taking into account the warning information provided in these Operating Instructions.

The general and domestic installation and safety regulations for work on electrical power equipment (e.g. VDE) must be observed as well as the professional handling of tools and the use of personal protective equipment.

Death, severe bodily injury or significant material damage could result if these instructions are not followed.

Clearances

When you install the equipment, make sure that the DC link connection is at the top and the motor connection is at the bottom.

The devices can be mounted side by side in close physical contact.

In order to ensure an adequate supply of cooling air, a clearance of 100 mm must be left at the top of the unit and at the bottom of the unit respectively to components which may considerably affect the flow of cooling air.

When mounting in cabinets, the cabinet cooling must be designed according to the power loss. Please refer to the Technical Data in this regard.

Requirements at the point of installation

- Foreign particles
 - The units must be protected against the ingress of foreign particles as otherwise their function and operational safety cannot be ensured.
- Dust, gases, vapors Equipment rooms must be dry and dust-free. Ambient and cooling air must not contain any electrically conductive gases, vapors and dust which could diminish the functionality. If necessary, filters should be used or other corrective measures taken.
- Cooling air

The units must only be operated in an ambient climate in accordance with DIN IEC 721-3-3 Class 3K3. For cooling air temperatures of more than 45 °C (113 °F) and installation altitudes higher than 1000 m, derating is required.

Installation 10.98




Fig. 5-1 Minimum clearances for cooling

Installation

The unit is mounted directly to a mounting surface. Fixing is by means of two or four M5 screws.




Fig. 5-2 Dimension drawings for housings up to 90 mm wide

10.98 Installation




Fig. 5-3 Dimension drawings for housings 135 mm and 180 mm wide

5.2 Installing the optional boards

WARNING



The unit has hazardous voltage levels up to 5 minutes after it has been powered down due to the DC link capacitors. The unit or the DC link terminals must not be worked on until at least after this delay time.

5.2.1 Installing optional boards on units with a width up to 90 mm

Disconnecting the rectifier unit from the mains

Disconnect the rectifier unit from the power supply and and switch OFF the unit. Remove the 24V power supply for the electronics. Take off all connecting leads.

Dismantling the unit

Dismantle the unit as follows:

- Open the terminals of the DC link bus module.
- Remove the fixing screws by means of which the unit is fixed to the mounting surface.
- Pull the unit down until the DC link bus module is completely exposed.
- Pull the unit out towards you.
- Lay the unit on its left side.

Opening the unit

- Unscrew the two fixing screws of the right-hand side wall. The fixing screws are located at the top of the unit at the rear right-hand corner, and at the bottom of the unit in the middle of the right-hand side wall.
- You do not have to remove the two fixing screws completely, as the wall of the unit is provided with a cutout to enable you to swing out the cover once the screws have been loosened.
- Open the right-hand side wall. To open it, swing the right-hand side wall towards you and pull it upwards out of the guide on the front edge

Removing the slot cover

- Remove the cover of the selected slot on the front panel.
- ◆ To do so, you must carefully cut through the four connecting points of the cover on the front panel with a thin knife.

10.98 Installation




Fig. 5-4 Position of the fixing screws on the right-hand side wall




Fig. 5-5 Removing the right-hand side wall

Installation 10.98

Installing the optional board

Push the optional board from behind into the opening on the front cover (①) until the position of the 64-pole system connector on the main board corresponds with the position of the socket.

Insert the optional board from the right onto the 64-pole system connector on the main board (②). The view shows the installed state.

Screw the optional board tight at the fastening points in the front section of the optional board (3).




Fig. 5-6 Installing the optional board

Assembling and mounting the unit

Close the right-hand side wall of the unit as follows

- Insert the right-hand side wall from above into the guide on the front right-hand side.
- Swing back the side wall.
- Screw the side wall tight again by means of the two fixing screws.

Mount the unit as follows:

- ◆ Insert the unit into its mounting position from the front underneath the DC link bus module.
- Lift the unit upwards until the DC link bus module is completely in its original position again.
- Screw the unit tight to the mounting surface with the fixing screws.
- Interlock the DC bus module.
- Re-connect all previously removed connecting cables.
- Check all connecting cables and the shield to make sure they sit properly and are in the correct position.

Designating the optional board

- ◆ To designate the optional board, insert the relevant designation plate into the envisaged position on the front of the unit.
- ◆ After powering up the voltage, you can log on the optional boards in the software of the unit and commence start-up.

10.98 Installation

5.2.2 Installing optional boards on units with a width of 135 mm and 180 mm

Disconnecting the rectifier unit from the mains

Disconnect the rectifier unit from the power supply and and switch OFF the unit. Remove the 24V power supply for the electronics. Take off all connecting leads.

NOTE

In the case of units with mounting widths of 135 mm and 180 mm, optional boards can be fitted with the power section in place

Opening the unit

- Loosen the 2 fixing screws on the front of the unit at the top. There is no need to remove the screws completely, since cutouts are provided in the housing to permit the front to come away after the screws have been loosened.
- Carefully swing the upper front section forwards (approx. 30 °) away from the housing.
- ◆ At the power section, open the locking lever of the ribbon cable that connects up with the control electronics.
- Take off the front of the unit by moving it forwards.

Removing the slot cover

- Remove the cover of the selected slot on the front panel.
- ◆ To do so, you must carefully cut through the four connecting points of the cover on the front panel with a thin knife.

Removing the optional board

- Undo the two optional board screws by about one turn each.
- Loosen the connection between the system connector and the board so as to prevent any mechanical tension arising when the screws are fully unscrewed.
- Take out the optional board screws and remove the board.

Mounting the optional board

- ◆ Insert the optional board from the behind the broken-out slot conver (①) until the position of the 64-pole system connector on the electronic board corresponds with the position of the socket.
- Insert the option board into the 64-pole system connector on the electronic board (②).
- ◆ Screw the optional board tight at the fastening points in the front section of the optional board with the two screws (③).

Installation 10.98




Fig. 5-7 Installing the optional board

Assembling and mounting the unit

- Keep the front of the unit tilted about approximately 30 ° forwards and insert the cutout of the lower guide plate - approaching from below - into the strip on the power section.
- Insert the connection cable plug into the power section socket and close the locking lever.
- Carefully return the front of the unit into the housing. Make sure that the guide plates on the right-hand side of the front (viewed from the front) enter the housing cutouts.
- Screw the front of the unit securely to the power section with the two fixing screws.

Connecting up the unit

- Re-connect all previously removed connecting cables.
- Check all connecting cables and the shield to make sure they sit properly and are in the correct position.

Designating the optional board

- ◆ To designate the optional board, insert the relevant designation plate into the envisaged position on the front of the unit.
- ♦ After powering up the voltage, you can log on the optional boards in the software of the unit and commence start-up.

6 Installation in Conformance with EMC Regulations

have to be inserted.

The following contains a summary of general information and guidelines which will make it easier for you to comply with EMC and CE regulations.

- Ensure that there is a conductive connection between the housing of the converters or inverters and the mounting surface. The use of mounting surfaces with good conducting properties (e.g. galvanized steel plate) is recommended. If the mounting surface is insulated (e.g. by paint), use contact washers or serrated washers.
- All of the metal cabinet parts must be connected through the largest possible surface area and must provide good conductivity.
 If necessary, use contact washers or serrated washers.
- ◆ Connect the cabinet doors to the cabinet frame using grounding strips which must be kept as short as possible.
- For the connection between converter/inverter and motor, use shielded cables which have to be grounded on both sides over a large surface area.
 If the motor terminal box is of plastic, additional grounding strands
- The shield of the motor supply cable must be connected to the shield connection of the converter and to the motor mounting panel through the largest possible surface area.
- ◆ The motor cable shield must not be interrupted by output reactors, fuses or contactors.
- All signal cables must be shielded. Separate the signal cables according to signal groups.
 Do not route cables with digital signals unshielded next to cables with analog signals. If you use a common signal cable for both, the individual signals must be shielded from each other.
- Power cables must be routed separately away from signal cables (at least 20 cm apart). Provide partitions between signal cables and power cables. The partitions must be grounded.
- Connect the reserve cables/conductors to ground at both ends to achieve an additional shielding effect.
- Lay the cables close to grounded plates as this will reduce the injection of undesired signals.
- Eliminate any unnecessary cable lengths because these will produce additional coupling capacitances and inductances.

- Use cables with braided shields. Cables with foil shields have a shielding effect which is worse by a factor of five.
- Contactor operating coils that are connected to the same supply network as the inverter or that are located in close proximity of the inverter must be connected to overvoltage limiters (e.g. RC circuits, varistors).

You will find further information in the brochure "Installation Instructions for EMC-correct Installation of Drives" (Order No.: 6SE7087-6CX87-8CE0).

10.98 Connecting-up

7 Connecting-up

WARNING



SIMOVERT MASTERDRIVES units are operated at high voltages. The equipment must be in a no-voltage condition (disconnected from the supply) before any work is carried out!

Only professionally trained, qualified personnel must work on or with the units.

Death, severe bodily injury or significant property damage could occur if these warning instructions are not observed.

Hazardous voltages are still present in the unit up to 5 minutes after it has been powered down due to the DC link capacitors. Thus, the appropriate delay time must be observed before working on the unit or on the DC link terminals.

The power terminals and control terminals can still be live even when the motor is stationary.

If the DC link voltage is supplied centrally, the converters must be reliably isolated from the DC link voltage!

When working on an opened unit, it should be observed that live components (at hazardous voltage levels) can be touched (shock hazard).

The user is responsible that all the units are installed and connected-up according to recognized regulations in that particular country as well as other regionally valid regulations. Cable dimensioning, fusing, grounding, shutdown, isolation and overcurrent protection should be particularly observed.




Fig. 7-1 Connection overview of units up to 90 mm wide

10.98 Connecting-up




Fig. 7-2 Connection overview of units 135 mm wide




Fig. 7-3 Connection overview of units 180 mm wide

7.1 Power connections

Protective conductor

The protective conductor must be connected up both on the mains side and on the motor side.

On account of leakage currents through the interference-suppression capacitors, a minimum cross-section of 10 mm² must be used in accordance with VDE 0160. If mains connections with cross-sections less than 10 mm² are used, the following measures can be applied.

If the unit is mounted on a grounded mounting surface via a conductive connection, the protective conductor cross-section can be the same as that of the supply-cable conductor.

In the case of insulated installation or a poor conductive connection to the mounting surface, a separate protective conductor with a cross-section of 10 mm² can be connected up instead of the protective conductor of the mains connection.

10.98 Connecting-up

7.1.1 Power connections for units with a width up to 90 mm

Protective conductor

On top of the unit behind the DC link connection X3 is an extra protective conductor connection in the form of a threaded M4 bolt. It is used for connecting a protective conductor for units in isolated connection.

X3 - DC link bus module

The DC link bus module serves to supply the unit with electrical energy.

_			A V	
	Bar	Designation	Meaning	Range
	3	PE3	Protective conductor connection	
, <u> </u>	2	D/L-	DC link voltge -	DC 510 - 650 V
	1	C/L+	DC link voltage +	DC 510 - 650 V

Connectable cross-section: "Electro-plated copper" 3x10 mm, rounded off according to DIN 46433

Bar 1 is at the front when installed.

Table 7-1 DC link busbars

X2 – Motor connection



The motor connection is located at the lower section of the unit.

Terminal		Meaning	Range
	PE2	Protective conductor connection	120
-	U2	Phase U2 / T1	3 AC 0 V - 480 V
-	V2	Phase V2 / T2	3 AC 0 V - 480 V
\	W2	Phase W2 / T3	3 AC 0 V - 480 V

Connectable cross-section: 4 mm² (AWG 10)

Terminal PE2 is at the front when installed.

Table 7-2 Motor connection

The connector must be firmly screwed onto the housing to provide a reliable motor connection.

The motor cables must be dimensioned in accordance with VDE 298, Part 2.

After installation of the connector, the shield of the motor cable must be fixed to the shield plate through a large surface area.

Connecting-up 10.98

7.1.2 Power connections for units with a width of 135 mm and 180 mm

X3 - DC link bus module

The DC link bus module serves to supply the unit with electrical energy.

Bar	Designation	Meaning	Range
3	PE3	Protective conductor connection	A.
2	D/L-	DC link voltge -	DC 510 - 650 V
1	C / L+	DC link voltage +	DC 510 - 650 V

Connectable cross-section: "Electro-plated copper" 3x10 mm, rounded off according to DIN 46433

Bar 1 is at the front when installed.

Table 7-3 DC link busbars

X2 – Motor connection

PE	U2	V2	W2
	(Ø	0

The motor connection is to a terminal block at the bottom of the unit.

	Terminal Meaning		Range	
	PE	Protective conductor connection	3AC 380 - 480 V	
>	U2 / T1	Phase U2 / T1	3AC 380 - 480 V	
	V2 / T2	Phase V2 / T2	3AC 380 - 480 V	
_	W2 / T3	Phase W2 / T3	3AC 380 - 480 V	

Connectable cross-section:

Housing width 135 mm: 10 mm² (AWG 8) Housing width 180 mm: 16 mm² (AWG 6)

Viewed from the front, Terminal PE is at the left.

Table 7-4 Motor connection

10.98 Connecting-up

7.2 Control connections

Standard connections

The basic version of the unit is provided with the following control connections:

- external 24V supply, USS bus connection (RS485)
- ♦ serial interface for PC or OP1S
- control terminal strip.




Fig. 7-4 Overview of the standard connections

X100 - external DC24 V supply, USS bus

The 4-pole terminal strip serves to connect the external 24 V DC power supply (supply from the supply unit or an AC/AC converter) and for connecting a USS bus.

The USS bus connection is linked to the control electronics and the 9-pole Sub-D socket of the serial interface X103.

The bus terminating resistor can be switched in via switch S1 as required. The bus termination is switched in when the switch is in the upper position.

The termination has to be switched in whenever the unit is located at one end of the USS bus.

•	33	
·	34	
•	35	
•	36	

Terminal	Designation	Significance	Range
33	+24 V (in)	24 V DC power supply	DC 24 V
34	0 V	Reference potential	0 V
35	RS485P (USS)	USS bus connection	RS485
36	RS485N (USS)	USS bus connection	RS485

Connectable cross-section: 2.5 mm² (AWG 12)

Terminal 33 is at the top when installed.

Table 7-5 External 24 V supply, USS bus


The unit draws a current of 1 A from the 24 V power supply. When optional boards are plugged in, this increases to a maximum of 1.6 A.

10.98 Connecting-up

X101 - Control terminal strip

The following connections are provided on the control terminal strip:

- 4 combined digital inputs and outputs
- 2 additional digital inputs
- ♦ 1 analog input
- ♦ 1 analog output
- ♦ 24 V auxiliary voltage supply (max. 60 mA) for the inputs.



Terminal	Designation	Meaning	Range	
1	P24 AUX	Aux. voltage supply	DC 24 V / 60 mA	
2	M24 AUX	Reference potential	0 V 👌	
3	DIO1	Digital input/output 1	24 V, 10 mA / 20 mA	
4	DIO2	Digital input/output 2	24 V, 10 mA / 20 mA	
5 💉	DIO3	Digital input/output 3	24 V, 10 mA / 20 mA	
6	DIO4	Digital input/output 4	24 V, 10 mA / 20 mA	
7	DI5	Digital input 5	24 V, 10 mA	
8	DI6	Digital input 6	24 V, 10 mA	
9	AI+	Analog input +	11 bit + sign differential input:	
10	Al-	Analog input -	\pm 10 V / Ri = 40 k Ω	
11 10	AO	Analog output	11 bit + sign ± 10 V / 5 mA	
12	М АО	Ground analog output	1.	

Connectable cross-section: 1.5 mm² (AWG 16)

Terminal 1 is at the top when installed.

Table 7-6 Control terminal strip

X103 - Serial interface

It is possible to connect either an OP1S or a PC with RS232 or RS485 serial interface via the 9-pole SUB D socket. There are different connecting cables for the PC for the various transmission protocols. The 9-pole SUB D socket is internally coupled with the USS bus, thus enabling data exchange with other nodes linked via the USS bus. This interface is also used for loading software.

9、	0000	-5
6	0000	1

Pin	Designation	Meaning	Range
1	RS232 ID	Changeover to RS232 protocol	Low active
2	RS232 RxD	Receive data via RS232	RS232
3	RS485 P	Data via RS485 interface	RS485
4	Boot	Control signal for software update	Low active
5	M5 AUX	Reference potential to P5V	0 V
6	P5V	5 V aux. voltage supply	+5 V, max. 200 mA
7	RS232 TxD	Transmit data via RS232	RS232
8	RS485 N	Data via RS485 interface	RS485
9	M_RS232/485	Digital ground (choked)	

Table 7-7 Serial interface

10.98 Connecting-up

X533 - Safe OFF Option

With the safe OFF option, the power supply for pulse transmission in the power section can be interrupted by means of a safety relay. This ensures that the unit cannot produce a rotating field when it is located at a connected-up motor.

Even if the control electronics give start signals, the active part of the motor cannot move.

This allows mechanical work on the motor or on coupled machine parts to be performed with the power supply ON and without the motor being electrically isolated from the unit.

WARNINGS




NOTE

- ◆ The safe OFF option does not provide any electrical isolation between the motor terminals and the power section!
- When in the "safe OFF" condition, the motor terminals are live with hazardous voltage!

The safe OFF option is not suitabe for bringing a running motor to a quick stop, because the control signals are switched OFF and the motor is therefore braked by the coupled load only.

The safe OFF option consists of the safety relay and the terminals for the relay control with a checkback signal contact.

Terminal	Designation	Significance		Range	
4 4	P24	24 V DC		DC 24 V	
3	K1. a	Control terminal		44.	
2	K1. 12	NC contact	7	Imax = 1 A	
1	K1. 11	NC contact	340Y	24 V	



Terminal 1 is at the front when installed in units with housings up to 90 mm wide, and at the rear when installed in units with housings more than 90 mm wide.

Table 7-8 Terminal assignment for the "Safe OFF" option



8 Parameterization

The functions stored in the units are adapted to your specific application by means of parameters. Every parameter is clearly identified by its parameter name and its parameter number. In addition to the parameter name and number, many parameters also have a parameter index. These indices enable several values to be stored for a parameter under one parameter number.

Parameter numbers consist of a letter and a three-digit number. The upper-case letters P, U, H and L represent the parameters which can be changed, and the lower-case letters r, n, d and c represent the visualization parameters which cannot be changed.

Examples

DC Bus Volts r006 = 541 Parameter name: DC Bus volts

Parameter number: r006

Parameter index: Does not exist

Parameter value: 541 V

Src ON/OFF1 P554.2 = 20 Parameter name: Src ON/OFF1

Parameter number: P554
Parameter index: 2
Parameter value: 20

Parameters can be input as follows:

 Via the PMU parameterizing unit which is permanently mounted on the front of the units,

- Via the user-friendly optional OP1S operator control panel or
- ♦ Via a PC and the SIMOVIS service program.

The parameters stored in the units can only be changed under certain conditions. The following preconditions must be satisfied before they can be changed.

- The parameter must be a changeable parameter. (Designated by upper-case letters in the parameter number).
- Parameter access must be granted.
 (P053 = 6 for parameterizing via the PMU or the OP1S).
- The unit must be in a status which permits parameters to be changed. (Carry out initial parameterization only in powered-down status).
- The lock and key mechanism must not be activated (Deactivation by parameter reset to factory setting).

Parameterization 10.98

8.1 Parameter input via the PMU

The PMU parameterizing unit enables parameterization, operator control and visualization of the converters and inverters directly on the unit itself. It is an integral part of the basic units. It has a four-digit seven-segment display and several keys.




Fig. 8-1 PMU parameterizing unit

Key	Significance	Function			
P	Toggle key	 For switching between parameter number, parameter index and parameter value in the sequence indicated (command becomes effective when the key is released). If fault display is active: Acknowledge the fault 			
	Raise key	For increasing the displayed value: Short press = single-step increase Long press = rapid increase			
	Lower key	For lowering the displayed value: • Short press = single-step decrease • Long press = rapid decrease			
P +	Hold toggle key and press raise key	If parameter number level is active: For jumping back and forth between the last selected parameter number and the operating display (r000) If fault display is active: For switching over to parameter number level			
	newhice.	If parameter value level is active: For shifting the displayed value one digit to the right if parameter value cannot be displayed with 4 figures (left-hand figure flashes if there are any further invisible figures to the left)			
P + 🔯	 Hold toggle key and press lower key If parameter number level is active: For jumping directly to the operating display (r000) If parameter value level is active: For shifting the displayed value one digit to the left if parameter value cannot be displayed with 4 figures (right-hand figure flashes if there are any further invisible figures to the right) 				

Table 8-1 Operator control elements on the PMU

Toggle key (P key)

As the PMU only has a four-digit seven-segment display, the 3 descriptive elements of a parameter


- Parameter number,
- Parameter index (if the parameter is indexed) and
- Parameter value

cannot be displayed at the same time. For this reason, you have to switch between the individual descriptive elements by depressing the toggle key. After the desired level has been selected, adjustment can be made using the raise key or the lower key.

With the toggle key, you can change over:

- from the parameter number to the parameter index
- from the parameter index to the parameter value
- from the parameter value to the parameter number

If the parameter is not indexed, you can jump directly from the parameter number to the parameter value.



NOTE

If you change the value of a parameter, this change generally becomes effective immediately. It is only in the case of acknowledgement parameters (marked in the parameter list by an asterisk ' * ') that the change does not become effective until you change over from the parameter value to the parameter number.

Parameter changes made using the PMU are always safely stored in the EEPROM (protected in case of power failure) once the toggle key has been depressed.

Example

The following example shows the individual operator control steps to be carried out on the PMU for a parameter reset to factory setting.


Set P053 to 0002 and grant parameter access via PMU



Select P060




Set P060 to 0002 and select "Fixed settings" menu



Select P970



Set P970 to 0000 and start parameter reset



8.2 Parameter input via the OP1S

The operator control panel (OP1S) is an optional input/output device which can be used for parameterizing and starting up the units. Plaintext displays greatly facilitate parameterization.

The OP1S has a non-volatile memory and can permanently store complete sets of parameters. It can therefore be used for archiving sets of parameters. The parameter sets must be read out (upread) from the units first. Stored parameter sets can also be transferred (downloaded) to other units.

The OP1S and the unit to be operated communicate with each other via a serial interface (RS485) using the USS protocol. During communication, the OP1S assumes the function of the master whereas the connected units function as slaves.

The OP1S can be operated at baud rates of 9.6 kBd and 19.2 kBd, and is capable of communicating with up to 32 slaves (addresses 0 to 31). It can therefore be used both in a point-to-point link (e.g. during initial parameterization) and within a bus configuration.

The plain-text displays can be shown in one of five different languages (German, English, Spanish, French, Italian). The language is chosen by selecting the relevant parameter for the slave in question.

Order numbers

Components	Order Number
OP1S	6SE7090-0XX84-2FK0
Connecting cable 3 m	6SX7010-0AB03
Connecting cable 5 m	6SX7010-0AB05
Adapter for installation in cabinet door incl. 5 m cable	6SX7010-0AA00

NOTE

The parameter settings for the units connected to the OP1S are given in the corresponding documentation of the unit (Compendium).




Fig. 8-2 View of the OP1S




Fig. 8-3 Example: The OP1S in a point-to-point link with the Compact PLUS unit

NOTE

In the as-delivered state or after a reset of the parameters to the factory setting, a point-to-point link can be adopted with the OP1S without any further preparatory measures and parameterization can be commenced.

Key	Significance	Function
	ON key	For energizing the drive (enabling motor activation). The function must be enabled by means of parameterization.
0	OFF key	For de-energizing the drive by means of OFF1, OFF2 or OFF3, depending on parameterization. This function must be enabled by means of parameterization.
Jog	Jog key	For jogging with jogging setpoint 1 (only effective when the unit is in the "ready to start" state). This function must be enabled by means of parameterization.
	Reversing key	For reversing the direction of rotation of the drive. The function must be enabled by means of parameterization.
P	Toggle key	For selecting menu levels and switching between parameter number, parameter index and parameter value in the sequence indicated. The current level is displayed by the position of the cursor on the LCD display (the command comes into effect when the key is released).
20,	20°	For conducting a numerical input
Reset	Reset key	For leaving menu levels
, tolerat	^r Q _c	If fault display is active, this is for acknowledging the fault. This function must be enabled by means of parameterization.
	Raise key	For increasing the displayed value:
	2410	Short press = single-step increase
The state of the s	My.	Long press = rapid increase
): 	f0/2)	If motorized potentiometer is active, this is for raising the setpoint. This function must be enabled by means of parameterization
	Lower key	For lowering the displayed value:
	.4500	Short press = single-step decrease
"ALM"	May 10	Long press = rapid decrease
1	14.	If motorized potentiometer is active, this is for lowering the setpoint. This function must be enabled by means of parameterization.
+/-	Sign key	For changing the sign so that negative values can be entered
9 to 0	Number keys	Numerical input

Table 8-2 Operator control elements of the OP1S


NOTE

If you change the value of a parameter, the change does not become effective until the toggle key (P) is pressed.


Parameter changes made using the OP1S are always stored safely in the EEPROM (protected in case of power failure) once the toggle key (P) has been pressed.

Some parameters may also be displayed without a parameter number, e.g. during quick parameterization or if "Fixed setting" is selected. In this case, parameterization is carried out via various sub-menus.

Example of how to proceed for a parameter reset.



Selection of fixed setting



Selection of factory setting



Start of factory setting


NOTE

It is not possible to start the parameter reset in the "Run" status.

8.3 Parameter reset to factory setting

The factory setting is the defined initial state of all parameters of a unit. The units are delivered with this setting.

You can restore this initial state at any time by resetting the parameters to the factory setting, thus canceling all parameter changes made since the unit was delivered.



Grant parameter access

Parameter changes permitted via PMU and serial interface SCom1 (OP1S and PC)

Menu selection "Fixed settings'

Select desired factory setting

0: Standard

Note: This parameter was correctly set prior to despatch of

the unit and only needs to be changed in exceptional

cases.

Start parameter reset

0: Parameter reset

1: No parameter change

Unit carries out parameter reset and goes into status 5 "Drive setting"

Fig. 8-4 Sequence for parameter reset to factory setting


8.4 Parameterizing by download

Downloading with OP1S

The OP1S operator control panel is capable of upreading parameter sets from the units and storing them. These parameter sets can then be transferred to other units by download. Downloading with the OP1S is thus the preferred method of parameterizing replacement units in a service case.

During downloading with the OP1S, it is assumed that the units are in the as-delivered state. The parameters for the power section definition are thus not transferred (see section "Detailed parameterization, power section definition"). If a PIN has been entered to release optional technology functions, this is also not overwritten during downloading.


With the "OP: Download" function, a parameter set stored in the OP1S can be written into the connected slave. Starting from the basic menu, the "OP: Download" function is selected with "Lower" or "Raise" and activated with "P".



Example: Selecting and activating the "Download" function

Now one of the parameter sets stored in the OP1S has to be selected using the "Lower" or "Raise" keys (displayed in the second line). The selected ID is confirmed with the "P" key. Now the slave ID can be displayed with "Lower" or "Raise". The slave ID contains various characteristic features of the unit such as rated output, order number, software version, etc.


The "Download" procedure is then started with the "P" key. During download, the OP1S displays the parameter currently being written.



Example: Confirming the ID and starting the "Download" procedure

With "Reset", the procedure can be stopped at any time. If downloading has been fully completed, the message "Download ok" appears and the display returns to the basic menu.

After the data set to be downloaded has been selected, if the identification of the stored data set does not agree with the identification of the connected unit, an error message appears for approximately 2 seconds. The operator is then asked if downloading is to be discontinued.



Yes: Downloading is discontinued.

No: Downloading is carried out.

8.5 Parameterizing with parameter modules

Pre-defined, function-assigned parameter modules are stored in the units. These parameter modules can be combined with each other, thus making it possible to adjust your unit to the desired application by just a few parameter steps. Detailed knowledge of the complete parameter set of the unit is not required.

Parameter modules are available for the following function groups:


- 1. Motors
- 2. Motor encoders
- 3. Control types
- 4. Setpoint and command sources


Parameterization is effected by selecting a parameter module from each function group and then starting quick parameterization.

Depending on your selection, the necessary unit parameters are set to produce the desired control functionality. The parameters necessary for fine adjustment of the control structure are automatically adopted in the user menu.

NOTE

If parameter changes have already been carried out on the unit, it is recommended that you carry out a parameter reset to the factory setting prior to performing "Quick parameterization".





Start quick parameterization

- 0: No parameter change
- 1: Parameter change according to selected combination of parameter modules

Note:

After the start, first of all an automatic factory setting is carried out with P366 = 0, then the relevant parameterization is performed.

Return to the user menu

Fig. 8-5 Sequence for parameterizing with parameter modules

Function diagram modules


Function diagram modules (function diagrams) are shown after the flow chart for parameter modules stored in the unit software. On the first few pages are the:


- setpoint and command sources, on the following pages are the
- analog outputs and the display parameters and the
- open-loop and closed-loop control types.


It is therefore possible to put together the function diagrams to exactly suit the selected combination of setpoint/command source and open/closed-loop control type. This will give you an overview of the functionality parameterized in the units and of the necessary assignment of the terminals.


The function parameters and visualization parameters specified in the function diagrams are automatically adopted in the user menu and can be visualized or changed there.

The parameter numbers of the user menu are entered in P360.









Motor list 1FK6 / 1FT6

		all a			
Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]	
1	1FK6032-6AK7	6000	0,8	1.5	
2	1FK6040-6AK7	6000	0.8	1.8	
3	1FK6042-6AF7	3000	2.6	2.4	
4	1FK6060-6AF7	3000	4.0	3.1	
5	1FK6063-6AF7	3000	6.0	4.9	
6	1FK6080-6AF7	3000	6.8	5.3	
7	1FK6083-6AF7	3000	10.5	7.8	
8	1FK6100-8AF7	3000	12.0	9.0	
9	1FK6101-8AF7	3000	15.5	10.8	
10	1FK6103-8AF7	3000	16.5	11.6	
11	1FT6031-4AK7_	6000	0.75	1.2	
12	1FT6034-1AK73A 1FT6034-4AK7_	6000	1.4	2.1	
13	1FT6041-4AF7_	3000	2.15	1.7	
14	1FT6041-4AK7_	6000	1.7	2,4	
15	1FT6044-1AF73A 1FT6044-4AF7_	3000	4.3	2.9	
16	1FT6044-4AK7_	6000	3.0	4.1	
17	1FT6061-6AC7_	2000	3.7	1.9	
18	1FT6061-1AF73A 1FT6061-6AF7_	3000	3.5	2.6	
19	1FT6061-6AH7_	4500	2.9	3.4	
20	1FT6061-6AK7_	6000	2.1	3.1	
21	1FT6062-6AC7_	2000	5.2	2.6	
22	1FT6062-1AF73A 1FT6062-6AF7_	3000	4.6	3.4	
23	1FT6062-6AH7_	4500	3.6	3.9	
24	1FT6062-6AK7_	6000	2.1	3.2	
25	1FT6064-6AC7_	2000	8.0	3.8	
26	1FT6064-1AF73A 1FT6064-6AF7_	3000	7.0	4.9	
27	1FT6064-6AH7_	4500	4.8	5.5	
28	1FT6064-6AK7_	6000	2.1	3.5	
29	1FT6081-8AC7_	2000	7.5	4.1	
30	1FT6081-8AF7_	3000	6.9	5.6	
31	1FT6081-8AH7_	4500	5.8	7.3	
32	1FT6081-8AK7_	6000	4.6	7.7	
33	1FT6082-8AC7_	2000	11.4	6.6	
34	1FT6082-1AF71A 1FT6082-8AF7_	3000	10.3	8.7	

Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]	
35	1FT6082-8AH7_	4500	8.5	11.0	
36	1FT6082-8AK7_	6000	5.5	9.1	
37	1FT6084-8AC7_	2000	16.9	8.3	
38	1FT6084-1AF71A 1FT6084-8AF7_	3000	14.7	11.0	
39	1FT6084-8AH7_	4500	10.5	12.5	
40	1FT6084-8AK7_	6000	6.5	9.2	
41	1FT6084-8SC7_	2000	23.5	12.5	
42	1FT6084-8SF7_	3000	22.0	17.0	
43	1FT6084-8SH7_	4500	20.0	24.5	
44	1FT6084-8SK7_	6000	17.0	25.5	
45	1FT6086-8AC7_	2000	23.0	10.9	
46	1FT6086-1AF71A 1FT6086-8AF7_	3000	18.5	13.0	
47	1FT6086-8AH7_	4500	12.0	12.6	
48	1FT6086-8SC7_	2000	33.0	17.5	
49	1FT6086-8SF7_	3000	31.0	24.5	
50	1FT6086-8SH7_	4500	27.0	31.5	
51	1FT6086-8SK7_	6000	22.0	29.0	
52	1FT6102-8AB7_	1500	24.5	8.4	
53	1FT6102-1AC71A 1FT6102-8AC7_	2000	23.0	11.0	
54	1FT6102-8AF7_	3000	19.5	13.2	
55	1FT6102-8AH7_	4500	12.0	12.0	
56	1FT6105-8AB7_	1500	42.0	14.5	
57	1FT6105-1AC71A 1FT6105-8AC7_	2000	38.0	17.6	
58	1FT6105-8AF7_	3000	31.0	22.5	
59	1FT6105-8SB7_	1500	57.0	21.5	
60	1FT6105-8SC7_	2000	55.0	28.0	
61	1FT6105-8SF7_	3000	49.0	35.0	
62	1FT6108-8AB7_	1500	61.0	20.5	
63	1FT6108-8AC7_	2000	55.0	24.5	
64	1FT6108-8SB7_	1500	83.0	31.0	
65	1FT6108-8SC7_	2000	80.0	39.0	
66	1FT6132-6AB7_	1500	62.0	19.0	
67	1FT6132-6AC7_	2000	55.0	23.0	
68	1FT6132-6AF7_	3000	36.0	23.0	
69	1FT6132-6SB7_	1500	100.0	36.0	

Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]
70	1FT6132-6SC7_	2000	98.0	46.0
71	1FT6132-6SF7_	3000	90.0	62.0
72	1FT6134-6AB7_	1500	75.0	24.0
73	1FT6134-6AC7_	2000	65.0	27.0
74	1FT6134-6SB7_	1500	130.0	45.0
75	1FT6134-6SC7_	2000	125.0	57.0
76	1FT6134-6SF7_	3000	110.0	72.0
77	1FT6136-6AB7_	1500	88.0	27.0
78	1FT6136-6AC7_	2000	74.0	30.0
79	1FT6136-6SB7_	1500	160.0	55.0
80	1FT6136-6SC7_	2000	150.0	72.0
81	1FT6108-8SF7_	3000	70.0	53.0

Table 8-3 Motor list 1FK6 / 1FT6

Motor list 1PA6 / 1PL6

Input in P097	Motor order number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]	
1	1PA6101-4_F	1750	24	9.0	
2	1PA6103-4_D	1150	36	9.6	
3	1PA6103-4_F	1750	34	12.7	
4	1PA6103-4_G	2300	31	15.4	
5	1PA6105-4_F	1750	44 📈	16.2	
6	1PA6107-4_D	1150	60	16.0	
7	1PA6107-4_F	1750	57	20.1	
8	1PA6131-4_F	1750	71	23.7	
9	1PA6133-4_D	1150	112	27.5	
10	1PA6133-4_F	1750	96	33.1	
11	1PA6133-4_G	2300	93	42.3	
12	1PA6135-4_F	1750	117	40.0	
13	1PA6137-4_D	1150	162	40.6	
14	1PA6137-4_F	1750	136	53.0	
15	1PA6137-4_G	2300	127	53.9	
16	1PA6163-4_B	400	227	28.2	
17	1PA6163-4_D	1150	208	52.1	
18	1PA6163-4_F	1750	185	69.0	
19	1PA6163-4_G	2300	158	78.5	
20	1PA6163-4_B	400	310	35.6	
21	1PA6167-4_D	1150	257	66.4	
22	1PA6167-4_F	1750	224	75.2	
23	1PA6184-4_B	400	390	51.0	
24	1PA6184-4_D	1150	366	89.0	
25	1PA6184-4_F	1750	325	122.0	
26	1PA6184-4_L	2900	265	158.0	
27	1PA6186-4_B	400	506	68.0	
28	1PA6186-4_D	1150	485	116.0	
29	1PA6186-4_F	1750	465	168.0	
30	1PA6186-4_L	2900	333	205.0	
31	1PA6224-4_B	400	725	89.0	
32	1PA6224-4_D	1150	670	162.0	
33	1PA6224-4_F	1750	605	205.0	
34	1PA6224-4_L	2900	490	275.0	
35	1PA6226-4_B	400	935	116.0	
36	1PA6226-4_D	1150	870	200.0	
37	1PA6226-4_F	1750	737	255.0	
38	1PA6226-4_L	2900	610	35.0	

Input in P097	- 1 1		Torque T _n [Nm]	Current In [A]	
39	1PA6228-4_B	400	1145	13.8	
40	1PA6228-4_D	1150	<u>\alpha</u> 1070	24.0	
41	1PA6228-4_F	1750	945	35.0	
42	1PA6228-4_L	2900	710	40.5	
43	1PL6184-4_B	400	585	6.9	
44	1PL6184-4_D	1150	540	12.1	
45	1PL6184-4_F	1750	486	16.6	
46	1PL6184-4_L	2900	372	20.9	
47	1PL6186-4_B	400	752	9.0	
48	1PL6186-4_D	1150	706	15.8	
49	1PL6186-4_F	1750	682	23.1	
50	1PL6186-4_L	2900	494	28.4	
51	1PL6224-4_B	400	1074	11.7	
52	1PL6224-4_D	1150	997	21.8	
53	1PL6224-4_F	1750	900	29.2	
54	1PL6224-4_L	2900	675	36.5	
55	1PL6226-4_B	400	1361	14.5	
56	1PL6226-4_D	1150	1287	27.5	
57	1PL6226-4_F	1750	1091	35.5	
58	1PL6226-4_L	2900	889	48.5	
59	1PL6228-4_B	400	1719	18.1	
60	1PL6228-4_D	1150	1578	33.4	
61	1PL6228-4_F	1750	1448	47.3	
62	1PL6228-4_L	2900	988	53.4	

Table 8-4 Motor list 1PA6 / 1PL6

8.6 Complete parameterization

To make full use of the complete functionality of the inverter/converter, parameterization must be carried out in accordance with the "Compendium". You will find the relevant instructions, function diagrams and complete lists of parameters, binectors and connectors in the Compendium.

Language	Compendium order number
German	6SE7080-0QX50
English	6SE7087-6QX50
French	6SE7087-7QX50
Spanish	6SE7087-8QX50
Italian	6SE7087-2QX50

9 Maintenance

WARNING



SIMOVERT MASTERDRIVES units are operated at high voltages. All work carried out on or with the equipment must conform to all the national electrical codes (VBG 4 in Germany).

Maintenance and service work may only be executed by qualified personnel.

Only spare parts authorized by the manufacturer may be used. The prescribed maintenance intervals and also the instructions for repair and replacement must be complied with.

Hazardous voltages are still present in the drive units up to 5 minutes after the converter has been powered down due to the DC link capacitors. Thus, the unit or the DC link terminals must not be worked on until at least after this delay time.

The power terminals and control terminals can still be at hazardous voltage levels even when the motor is stationary.

If it is absolutely necessary that the drive converter be worked on when powered-up:

- Never touch any live parts.
- Only use the appropriate measuring and test equipment and protective clothing.
- ♦ Always stand on an ungrounded, isolated and ESD-compatible pad.

If these warnings are not observed, this can result in death, severe bodily injury or significant material damage.

Maintenance 10.98

9.1 Replacing the fan

A fan is mounted at the lower section of the inverter for cooling the power section.

The fan is fed by the 24 V supply voltage and switched on and off by electronic control according to the heat sink temperature.

The fan is designed for a service life of $L_{10} \ge 35{,}000$ hours and an ambient temperature of $T_u = 45$ °C. It must be exchanged in good time to ensure the availability of the unit.

9.1.1 Replacing the fan in units up to 90 mm wide

Removal

To replace the fan, the inverter has to be disconnected from the supply and removed.

After removing the X20 connector which is protected against polarity reversal and carefully bending up the fastening clips the fan can be taken out.

Installation

When installing the new fan, attention has to be paid to the correct direction of the air flow. The air must flow into the inside of the unit (see directional arrow on the fan housing).

9.1.2 Replacing the fan in units 135 mm wide

Removal

- Before you exchange the fan, the converter must be disconnected from the power supply and removed.
- Undo the four fan mounting screws and take out the fan.
- Disconnect the leads on the fan.

Fitting the new fan

- Fit the new fan in the reverse order.
- Make sure that the arrow indicating the direction of air flow points to the inside of the unit.

NOTE

Make sure that the fan leads are connected the right way round. Otherwise the fan will not operate!

10.98 Maintenance

9.1.3 Replacing the fan in units up to 180 mm wide

Two fans are mounted on the lower side of the converter, an **internal** fan for cooling the control electronics and a **unit fan** for cooling the power section.

Both fans are fed by the 24 V voltage supply; the unit fan is switched on and off by electronic control according to the heat sink temperature.

The fans are designed for a service life of $L_{10} \ge 35\,000$ hours at an ambient temperature of $T_u = 45\,^{\circ}\text{C}$. They must be replaced in good time to ensure the availability of the unit.

Internal fan

- ♦ Before removing the old fan and fitting a new one, make sure that the inverter is disconnected from the power supply.
- Opening the unit:
 - Loosen the 2 mounting screws in the front at the top of the unit.
 There is no need to take the screws right out. Slots are provided in the housing to allow the front of the unit to be released when the screws have been loosened.
 - Carefully swing the front of the unit forwards (to an angle of about 30°) away from the housing.
 - On the power section, open the locking lever on the ribbon cable connector to the control electronics.
 - · Move the cover forwards and take it off.
- Remove the fan connection X20 on the power section.
- Undo the four fan mounting screws and take out the fan.
- Fit the new fan by reversing this sequence of operations. Make sure that the arrow indicating the direction of rotation is pointing to the inside of the unit.

Unit fan

- ◆ The converter must be disconnected from the power supply and removed before the fan can be replaced.
- Undo the four fan mounting screws and take out the fan.
- Disconnect the leads on the fan.
- Fit the new fan in the reverse order.
- Make sure that the arrow indicating the direction of air flow points to the inside of the unit.

NOTE

Make sure that the leads to the fan are connected the right way round. Otherwise the fan will not operate!

10.98 Forming

10 Forming

If a unit has been non-operational for more than one year, the DC link capacitors have to be newly formed. If this is not carried out, the unit can be damaged when the line voltage is powered up.

If the unit was started-up within one year after having been manufactured, the DC link capacitors do not have to be re-formed. The date of manufacture of the unit can be read from the serial number.

How the serial number is made up

(Example: RFU-J60147512345)

Position	Example	Meaning		
1 to 3	RFU-	Place of manufacture		
4	John	1997		
	K	1998		
	L	1999		
	М	2000		
5	1 to 9	January to September		
	0 10	October		
	N Colo	November		
	D	December		
6 to 15	8	Not relevant for forming		

The following applies for the above example: Manufacture took place in June 1997.

During forming, the DC link of the unit is connected up via a rectifier, a smoothing capacitor and a resistor.

As a result, the DC link capacitors receive a defined voltage and a limited current, and the internal conditions necessary for the function of the DC link capacitors are restored.




Fig. 10-1 Forming circuit

Components for the forming circuit (suggestion)

Rectifier (A): SKD 62/16

Resistor (R): 470 Ω, 100 W

◆ Capacitor (C): 22 nF, 1600 V

WARNING



Procedure

The unit has hazardous voltage levels up to 5 minutes after it has been powered down due to the DC link capacitors. The unit or the DC link terminals must not be worked on until at least after this delay time.

- Before forming the DC link capacitors, you must remove the unit or or remove the front and middle DC link busbars (C/L+ and D/L-).
- ♦ After you have removed the unit, connect PE2 to ground. Built-in units are to be grounded to busbar PE3.
- Connect up the forming equipment as shown in the circuit diagram.
- Switch on the forming circuit. The forming duration depends on the length of time that the inverter has been out of action.




Fig. 10-2 Forming time as a function of converter idle time

11 Technical Data

EC Low-Voltage Directive 73/23/EEC and RL93/68/EEC	EN 50178
EC EMC Directive 89/336/EWG	EN 61800-3
EC Machinery Safety Directive 89/392/EEC	EN 60204-1
Approvals	UL: E 145 153 CSA: LR 21 927 (For units with rated motor output from 5.5 kW: in preparation)
Type of cooling	Air-cooled with installed fan
Permissible ambient or coolant temperature • During operation	0° C to +45° C (32° F to 113° F)
During storage	(to 50° C, see fig. "Derating curves") -25° C to +55° C (-13° F to 131° F)
During transport	-25° C to +70° C (-13° F to 158° F)
Installation altitude	 ≤ 1000 m above sea level (100 per cent loadability) > 1000 m to 4000 m above sea level (Loadability: see fig. "Derating curves")
Permissible humidity rating	Relative air humidity $\leq 95 \%$ during transport and storage $\leq 85 \%$ in operation (condensation not permissible)
Environmental conditions to DIN IEC 721-3-3	Climate: 3K3 Chemically active substances: 3C1
Pollution degree	Pollution degree 2 to IEC 664-1 (DIN VDE 0110, Part 1), Moisture condensation during operation is not permissible
Overvoltage category	Category III to IEC 664-1 (DIN VDE 0110, Part 2)
Type of protection	IP20 EN 60529
Protection class	Class 1 to EN 536 (DIN VDE 0106, Part 1)
Shock-hazard protection	EN 60204-1 and to DIN VDE 0106 Part 100 (VBG4)
Radio interference level	According to EN 61800-3
Standard	No radio interference suppression
 Options 	Radio interference suppression filter for class B1 or A1 to EN 55011
Noise immunity	Industrial sector to EN 61800-3
Paint	Indoor duty

Technical Data

Mechanical strength - Vibration	According to DIN IEC 68-2-6
During stationary duty:	0.15 mm in frequency range 10 Hz to 58 Hz
const. amplitude	(housing width ≤ 90 mm)
deflection	0.075 mm in frequency range 10 Hz to 58 Hz (housing width ≥ 135 mm)
acceleration	9.8 m/s² in frequency range > 58 Hz to 500 Hz (housing width ≥ 135 mm)
During transport:	19.6 m/s² housing width ≤ 90 mm
 deflection 	3.5 mm in frequency range 5 Hz to 9 Hz
 accleration 	9.8 m/s² in frequency range > 9 Hz to 500 Hz
- Shocks	According to DIN IEC 68-2-27 / 08.89
	30 g, 16 ms half-sine shock
- Drop	According to DIN IEC 68-2-31 / 04.84
	onto a surface and onto an edge

Table 11-1 General data

10.98 Technical Data

Designation		1900	,	Value	1900	
Order No.	6SE70	12-0TP50	14-0TP50	16-0TP50	21-0TP50	21-3TP50
Rated voltage • Input • Output	[V]		DC 510 (- 15 %) to 650 (+ 10 %) 3 AC 0 up to rated input voltage x 0.64			2
Rated frequency • Input • Output	[Hz]	Holligish	<i>y</i>	 0 400		to natific
Rated current Input Output	[A]	2.5 2.0	5.0 4.0	7.5 6.1	12.5 10.2	15.7 13.2
Motor rated power	[kW]	0.75	1.5	2.2	4.0	5.5
Auxiliary power supply	∂ [V]		9	DC 24 (20 - 30))	6
Max. aux. current requi • Standard version at 2 • Maximum version at 2	0 V	, KOLLIGH,	0	0.8 1.5		to Logic Jros.
Pulse frequency fp	[kHz]	7000	5.0 to 10.0	(see fig. "Dera	ting curves")	
Load class II to EN 60	146-1-1	4.10	-41	٥,	- ch!	
Base load current	[A]	0.91 x rated output current				
Base load duration	[s]			300		
Overload current	[A]		1.6 x	rated output c	urrent	
Overload duration	[s]	27/		30		il Her
Extra short-time loading	9	"OLU		,0K°		*0[[]
Short-time current (fp =	5 kHz) [A]	Page 1	1 X E	rated output cu	ırrent	200
Short-time current (fp =	10 kHz)[A]		2.1 x	rated output o	urrent	
Short-time cycle	[s]		The state of	1	774	
Short-time duration	[ms]			250		
Loses, cooling	9		9	6		6
Efficiency η (rated oper	ation)	. J.	>	The		"The
Power loss (fp = 10 kHz	z) [kW]	0.066	0.086	0.116	0.156	0.240
Cooling air requirement	t [m³/s]	0.002	0.009	0.009	0.018	0.018
Pressure drop Δ p	[Pa]	1 0	20	20	15	15
Sound pressure levels,	types of cor	nstruction, dim	nensions, weig	hts	200	
Sound pressure level	[dB(A)]	18	40	40	37	37
Dimensions • Width • Height • Depth	[mm]	45 360 260	67.5 360 260	67.5 360 260	90 360 260	135 360 260
Weight approx.	[kg]	3	4	4	5	9.1


Table 11-2 Technical data of inverter (Part 1)


Designation		1200	d	Value	- 100	/
	E70	21-8TP50	22-6TP50	23-4TP50	23-8TP50	
Rated voltage • Input • Output	[V]			(- 15 %) to 650 o rated input vo	(+ 10 %)	3
Rated frequency Input Output	[Hz]	JEOPP BEST	9	 0 400		ich gight
Rated current Input Output	[A]	20.8 17.5	30.4 25.5	40.5 34.0	44.6 37.5	
Motor rated power	[kW]	7.5	11.0	15.0	18.5	
Auxiliary power supply	[V]		9	DC 24 (20 - 30)	9
Max. aux. current requireme • Standard version at 20 V • Maximum version at 20 V	nt [A]		.8 .1	, to matrix	0.8 2.4	Charlys
Pulse frequency fp	[kHz]	5.0 to 10.0 (see fig. "Derating curves")			ting curves")	
Load class II to EN 60 146-1	-1	4100	.44	-9	14/10	
Base load current	[A]		0.91 >	rated output o	current	
Base load duration	[s]			300		
Overload current	[A]	1.6 x rated output current			26	
Overload duration	[s]	2014		30		a de
Extra short-time loading	•	.050		. of 10		.0500
Short-time current (fp = 5 kH	lz) [A]	1812	3 x ı	ated output cu	rrent	>
Short-time current (fp = 10 k	Hz)[A]	740,	2.1 x	rated output c	urrent	
Short-time cycle	[s]					
Short-time duration	[ms]	250				
Loses, cooling	·		9	9		9
Efficiency η (rated operation)	- K	>	Mrs.		"Tho.
Power loss (fp = 10 kHz)	[kW]	0.300	0.410	0.550	0.660	- Clar.
Cooling air requirement	[m³/s]	0.041	0.041	0.061	0.061	9
Pressure drop Δp	[Pa]	30	30	30	30	
Sound pressure levels, type	s of cor	nstruction, dim	nensions, weig	hts	The same	
Sound pressure level [c	B(A)]	48	48	59	59	
Dimensions • Width • Height • Depth	[mm]	135 360 260	135 360 260	180 360 260	180 360 260	all shares
Weight approx.	[kg]	9.2	9.3	13.8	14.0	2

Table 11-3 Technical data of inverter (part 2)

10.98 Technical Data

Derating curves





Height [m]	Derating factor K ₁				
1000	1.0				
2000	0.9				
3000	0.845				
4000	0.8				
	-				

100		Caldy For			
75	70,5 gr			700	1310
50			3	4144	
25 —					_
0	10	20	30	40	_

Temp [°C]	Derating factor K ₂
50	0.879
45	1.0
40	1.125
35	1.25 *
30	1.375 *
25	1.5 *

*See note below

Fig. 11-1 Derating curves

Technical Data

The derating of the permissible rated current for installation altitudes of over 1000 m and at ambient temperatures below 45 °C is calculated as follows:

Total derating = Deratingaltitude x Deratingambient temperature $K = K_1 \times K_2$

NOTE

It must be borne in mind that total derating must **not be greater** than 1!

Example: Altitude: 3000 m $K_1 = 0.845$ Ambient temperature: 35 °C $K_2 = 1.25$ \Rightarrow Total derating = 0.845 x 1.25 = 1.056 (= 1)

Rating plate



Fig. 11-2 Rating plate

Date of manufacture The date of manufacture can be derived as follows:

Character	Year of manufacture:	Character	Month of manufacture
J	1997	1 to 9	January to September
K	1998	0	October
L	1999	Kapa N	November
М	2000	D	December

Table 11-4 Assignment of characters to the month and year of manufacture

10.98 Technical Data

Option codes

Option	Meaning	Option	Meaning
Ö,	SBP: Pusle encoder evaluation	Ġ,	CBP: Profibus
C11	Slot A	G11	Slot A
C12 C13	Slot B Slot C	G12 G13	Slot B Slot C
7/9	SBR1: Resolver evaluation	25	CBC: CAN bus
242	without pulse encoder simulation	G21	Slot A
C23	Slot C	G22	Slot B
	SBR2: Resolver evaluation with	G23	Slot C
X	pulse encoder simulation		EB1: Expansion Board 1
C33	Slot C	G61	Slot A
	SBM: Absolute-value encoder	G62	Slot B
.8	evaluation	G63	Slot C
C51	Slot A		EB2: Expansion Board 2
C52	Slot B	G71	Slot A
C53	Slot C	G72	Slot B
\$	SLB: SIMOLINK	© G73	Slot C
G41	Slot A	K80	"Safe OFF" option
G42	Slot B		1000
G43	Slot C		No. of the second

Table 11-5 Meaning of the option codes

12 Faults and Alarms

12.1 Faults

General information regarding faults

For each fault, the following information is available:

Parameter r947 Fault number

r949 Fault value r951 Fault list

P952 Number of faults

r782 Fault time

If a fault message is not reset before the electronic supply voltage is switched off, then the fault message will be present again when the electronic supply is switched on again. The unit cannot be operated without resetting the fault message. (Exception: Automatic restart has been selected, see P373).

Number / Fault	Cause	Counter-measure
F001	The monitoring time of the main contactor checkback (P600) has expired.	- Check main contactor checkback - Clear main contactor checkback (P591.B =
Main contactor checkback	- House	0) - Increase monitoring time (P600)
F002 Pre-charging fault	The monitoring time of pre-charging has expired, i.e. the DC link voltage has not reached the setpoint within 3 secs.	- Check voltage connection (AC or DC) - Compare value in P070 and unit MLFB
F006 DC link overvoltage	Due to excessive DC link voltage, shutdown has occurred (shutdown threshold approx. 820 V)	Check the line voltage (AC-AC) or the input direct voltage (DC-AC). Compare value with P071 (Line Volts)
F008 DC link undervoltage	The lower limit value of 76% of the DC link voltage has been fallen short of.	- Check the line voltage (AC-AC) or the input direct voltage (DC-AC). Compare value with P071 (Line Volts) - Check input rectifier (AC-AC) - Check DC link
F011 Overcurrent	Overcurrent shutdown has occurred. The shutdown threshold has been exceeded.	Check the converter output for short-circuit or earth fault Check the load for an overload condition
	Madi	Check whether motor and converter are correctly matched Check whether the dynamic requirements are too high

Number / Fault	Cauca	Counter macoure
	Cause	Counter-measure
F015	Motor is blocked/overloaded (current control),	- Reduce the load
Motor blocked	or has stalled (v/f characteristic):	- Release the brake
Motor blocked	Static load is too high	- Nelease the brake
	Static load is too riigii	- Increase current limits
	°S,	morease current limits
	The fault is not generated until after the time entered in P805.	- Increase P805 Blocking Time
	Chicica in 1 coo.	- Increase the response threshold for the
		permissible deviation P792
	Binector B0156 is set, in status word 2 r553 Bit	- Increase torque limits or torque setpoint
	28.	1/4
	May, May,	v/f characteristic only:
	Whether the drive is blocked or not can be	- Reduce rate of acceleration
	detected at P792 (Perm Deviation) and P794.	- Check characteristic setting.
	P806 enables detection to be limited to "at	73 ×
	standstill" (P806 = 1, only for current control)	30/2
	or to be completely de-activated (P806 = 2).	The Thirty
	In the case of current control, the precondition	10,
	for this fault is that the torque limits (B0234)	5 10 10 10 10 10 10 10 10 10 10 10 10 10
	have been reached.	(6)
	Tay.	Phy.
	In the case of slave drive, detection is deactivated.	The contract of the contract o
		2 2
	In the case of v/f control, the I(max) controller	, S,
F0.47	must be active.	" I OAFF OFFO
F017	SAFE OFF operating or failure of the 24 V	Jumper applied for SAFE OFF?
OAFF OFF	power supply during operation (only for	SAFE OFF checkback connected?
SAFE OFF	Compact PLUS units)	On Compact PLUS units: check 24 V supply
F020	The motor temperature limit value has been	- Temperature threshold adjustable in P381!
Evenes temperature of	exceeded.	D121 0 - foult do notiveted
Excess temperature of	r040 – 1 Motor tomporeture limit value	- P131 = 0 -> fault de-activated
motor	r949 = 1 Motor temperature limit value exceeded	- Check the motor (load, ventilation etc.)
	cxcccaca	Officer the motor (load, ventilation ctc.)
	r949 = 2 Short-circuit in the motor temperature	- The current motor temperature can be read
	sensor cable or sensor defective	in r009 (Motor Temperat.)
	785	
	r949 = 4 Wire break of motor temperature sensor cable or sensor defective	- Check the sensor for cable break, short-circuit
F021	Parameterized limit value of the I2t monitoring	Check: Thermal time constant of motor P383
1021	for the motor (P384.002) has been exceeded	Mot ThermT-Const or motor I2t load limit
Motor I2t	Tot the motor (1 do 1.002) had been exceeded	P384.002.
120	2, 2,	The I2t monitoring for the motor is
		automatically activated if P383 >=100s
	A A	(=factory setting) and P381 > 220°C is set.
	19×	Monitoring can be switched off by setting a
25	762	value <100s in P383.
F023	The limit value of the inverter temperature has	- Measure the air intake and ambient
	been exceeded	temperature.
Excess temperature of	7.95 7.0	7. 7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
inverter	(O) (O)	- Observe the derating curves at q > 50 °C
	Tay. Tay.	(Compact PLUS) or 40 °C
	Mr. Mr.	
		- Check whether the fan is running
	2	Chook that the six anti- and Park and
	. a.S.	- Check that the air entry and discharge
E025	LICE upper switch (Compact DLUS) / LICE	openings are not restricted
F025	UCE upper switch (Compact PLUS) / UCE Phase L1 (chassis-type unit)	- Check the converter outputs for earth fault
UCE upper switch/UCE	i nase Li (Giassis-type Utill)	- Check the switch for "Safe OFF" on Compact
Phase L1	200	units
F026	UCE lower switch (Compact PLUS) / UCE	- Check the converter outputs for earth fault
1 020	Phase L2 (Compact, chassis)	Check the converter outputs for earth fault
UCE lower switch/UCE	i nase Lz (Compact, chassis)	- Check the switch for "Safe OFF" on Compact
Phase L2		units
1 11430 LZ		unito

Number / Fault	Course	Counter massure
F027	Cause Pulse resistance fault (only Compact PLUS) /	- Check the converter outputs for earth fault
1021	UCE Phase L3 (chassis)	- Officer the converter outputs for earth fault
Pulse resistor fault /	002 (Mass 25 (Mass 15)	- Check the switch for "Safe OFF" on Compact
UCE Phase L3		units
F035	Parameterizable external fault input 1 has	- Check whether there is an external fault
×	been activated.	10 XO X
External fault 1		- Check whether the cable to the
	ALL.	corresponding digital output is interrupted
		- P575 (Src No ExtFault1)
F036	Parameterizable external fault input 2 has	- Check whether there is an external fault
. 555	been activated.	and the same of th
External fault 2	The The	- Check whether the cable to the
		corresponding digital output is interrupted
F000		- P576 (Src No ExtFault2)
F038	A voltage failure has occurred during a	Re-enter the parameter. The number of the parameter concerned is indicated in fault value
Voltage OFF during	parameter task.	r949.
parameter storage	10°	1949.
F040	Incorrect operating status	Replace the control board (CUMC) or the unit
(40)		(Compact PUS).
Internal fault of	The The	Tru,
sequence control	N. N.	74, 3
F041	A fault has occurred during the storage of	Replace the control board (CUMC) or the unit
EEDDOM foult	values in the EEPROM.	(Compact PLUS)
EEPROM fault F042	The available calculating time of the time slot	- Reduce pulse frequency
1 042	has been exceeded.	- Reduce pulse frequency
Time slot overflow	nac scori checoaca.	- Calculate individual blocks in a slower
		sampling time
F043	The link to the internal signal processor is	- Reduce pulse frequency (perhaps caused by
	interrupted	calculating time overflow)
DSP link	A C 161	- If fault re-occurs, replace the board/unit
F044	A fault has occurred in the softwiring of binectors and connectors	Fault value r949:
BICO manager fault	binectors and connectors	>1000: Fault during connector softwiring >2000: Fault during binector softwiring
bioo manager raun	18 S.	>2000. I duit during binector softwiring
	10 L	- Voltage OFF and ON
		- Factory setting and new parameterization
	- 180°	- Exchange the board
	200	4000 link manner in full. The link area
	76	1028:Link memory is full. The link area between the two processors is full. No further
	747.	connectors can be transferred.
	4.	
		- Reduction of the linked connections between
	~3, ~3,	the two processors. Interface between the two
	Fo. Tho.	processors is position control/setpoint
	, , , , , , , , , , , , , , , , , , ,	conditioning i.e.softwires from and to the
	101	setpoint conditioning, position controller, speed controller, torque interface and current
	~9 ₂	controller which are not necessary should be
	(b) (b)	dissolved to reduce the link (value 0).
F045	A hardware fault has occurred during access	- Replace CU board (Compact, chassis units)
2/2	to an optional board.	30
HW fault on optional		- Replace the unit (Compact PLUS)
boards	9 9	Chook the connection between the subject
	10×	- Check the connection betewen the subrack
	7 ¹ / ₂	and the optional boards
	ALCO.	- Replace optional boards.
F046	A fault has occurred during the transfer of	If fault re-occurs, replace the board/unit
	parameters to the DSP.	
Parameter coupling	71/2 A.C.	W.
fault		47

Number / Fault	Cause	Counter-measure
F051	- Signal amplitude of resolver or encoder is	Resolver/encoder
	below the tolerance threshold	fault value r949:
Encoder fault	- In the case of multiturn encoders (SSI/Endat)	9 = Resolver signal missing
	connection fault of the serial protocol	28 = Voltage supply Encoder fault
	A	- Short-circuit in encoder connection?
	1.8×	- Encoder faulty?
	The Table	- Encoder incorrectly connected up?
		29 = Encoder signal is missing
	, XO,	- Check encoder cable (faulty/torn off)?
		- Is shield of encoder cable connected?
	1,60	- Encoder faulty?
	. M	- Replace SBR/SBM
	74,	- Replace unit or basic board
	2, 2,	- Is the correct cable being used in each case
		for the encoder/multiturn encoder? Encoders
	A A	and multiturn encoders require different
	19%	encoder cables!
	70.	10 m
	40	Multiturn (SSI/EnDat):
	10°	Fault value r949:
	~% ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	30: Protocol fault CRC/Parity Check
	(3)	31: Timeout Protocol (EnDat)
	'A'. Ay.	32: Neutral level fault
	72,	33: Initialization of timeout
		- Check parameterization (P149)
		- Check encoder cable (faulty / torn off?
	9	- Encoder cable shield connected ?
	10°	- Encoder faulty?
	² 2),	- Replace SBR/SBM
	Jr. Mile	- Replace unit or basic board
	110	210.
	200	34: Address wrong (only EnDat)
	70,	Writing or reading of parameters not
	The state of the s	successful, check address and MRS code
	7, 7,	(P149)
		40-48: Encoder alarms (only EnDat)
	28,	Check voltage supply to encoder, battery
	The The	change on battery-backed-up systems,
	₹₽.,	encoder faulty?
		10x
	- 100 m	49: Alarm bit set
	.25	Parameterization (P149), Encoder alarm
	74. A.	_ ~h;
	The The	50-59: Alarms EnDat encoder
	2.	Facility and the second of the second of the
		Fault value + 100 designates the
FOFO	After the page have been as a delication of	corresponding faults of the external encoder.
F053	After changes have been made to parameters,	No remedy
Danamastan facilit	a fault has occurred during the calculation of	"id".
Parameter fault in	dependent parameters.	The The
follow-up task	×O,	×O. ×O.

Number / Fault	Cause	Counter-measure
F054	A fault has occurred during initialization of the	Fault value r949:
	encoder board.	1: Board code is incorrect
Encoder board	2, 2,	2: TSY not compatible
nitialization fault		3: SBP not compatible
Thilanzation radit		4: SBR not compatible
	° 0,	5: SBM not compatible
	FD.,	
	1, 20,	6: SBM initialization timeout
	400	7: Board double
	^X O,	*O,
		20: TSY board double
	190	21: SBR board double
	410	23: SB board three-fold
	30	24: SBP board three-fold
	2, 2,	24. OBI Board tirect fold
		30: SBR board slot incorrect
	~8,	31: SBM board slot incorrect
	15.	32: SBP board slot incorrect
	1, 29,	10,
	- CO	40: SBR board not present
	%O,	41: SBM board not present
		42: SBP board not present
	× × × × × × × × × × × × × × × × × × ×	12. ODI Dodia not prosont
	76	FO: Three anader beards
	77,00	50: Three encoder boards
	24, 24,	
		60: internal fault
F056	Communication on the SIMOLINK ring is	- Check the fiber-optic cable ring
	disturbed.	
SIMOLINK telegram	10°	- Check whether an SLB in the ring is without
ailure	16.	voltage
allule	Z.O.	voltage
	xO ¹	Objects whether a QLD is the steet to footbe
	100 m	- Check whether an SLB in the ring is faulty
	70,	, XO
750	70	- Check P741 (SLB TlgOFF)
F058	A fault has occurred during the processing of a	No remedy
	parameter task.	3/1
Parameter fault		
Parameter task		
F059	A fault has occurred in the initialization phase	The number of the inconsistent parameter is
-059		
	during the calculation of a parameter.	indicated in fault value r949. Correct this
Parameter fault after	400	parameter (ALL indices) and switch voltage o
factory setting/init.	XO),	and on again. Several parameters may be
	100 m	affected, i.e. repeat process.
F060	Is set if parameter P070 is at zero when	Enter correct MLFB after acknowledging the
750	INITIAL LOADING is exited.	fault (power section, initial loading)
MLFB is missing during	THE LOVE TO 15 CARCO.	radit (power decitors, initial loading)
	Mr. Mr.	The.
nitial loading		
F061	A parameter which has been entered during	The number of the inconsistent parameter is
	drive setting is in the non-permissible range.	indicated in fault value r949 (e.g. motor
Incorrect	10-2	enocder = pulse encoder in the case of
parameterization	The state of the s	brushless DC motors) -> correct this
-a.amotonzation	(A)	parameter.
E063	The synchronization or positioning technology	•
F063	The synchronization or positioning technology	- Deactivate synchronization or positioning
	functions have been activated without an	- Enter the PIN (U2977)
PIN is missing	authorization being present (PIN)	, (O)
F065	No telegram has been received at an SCom	Fault value r949:
	interface (SCom/USS protocol) within the	26,
SCom telegram failure	telegram failure time.	1 = Interface 1 (SCom1)
2 2 2 to.ogram landio		2 = Interface 2 (SCom2)
	9	2 = 111011400 2 (0001112)
	19×	Charletha connection of DMLL VOCA or V400
	K. "The	Check the connection of PMU -X300 or X103
		27,28 (Compact, chassis unit)
	76.	The state of the s
	30	Check the connection of X103 or X100 / 35,36
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	(Compact PLUS unit)
	(0)	(Compact i LOS unit)
	Mr. Mr.	Oh ask 1100 am (COD TI-Off! D704 04 (CO
	7.0	Check "SCom/SCB TlgOff" P704.01 (SCom1)
	The The	or P704.02 (SCom2)

Number / Fault	Cause	Counter-measure
F070	A fault has occurred during initialization of the SCB board.	Fault value r949:
SCB initialization fault	202 200.31	1: Board code incorrect
oob iiiiiaiizatioii iaati		2: SCB board not compatible
		5: Error in configuration data
	"S.	6: Initialization timeout
	to "The	7: SCB board double
	3	10: Channel error
F072	A fault has occurred during initialization of the	Fault value r949:
1072	EB board.	2: 1st EB1 not compatible
EB initialization fault	EB board.	3: 2nd EB1 not compatible
LB IIIIIalization laut	250	4: 1st EB2 not compatible
	The state of the s	5: 2nd EB2 not compatible
	27,	21: Three EB1 boards
		22: Three EB2 boards
	5.	440. Fault are 4at FD4
	The The	110: Fault on 1st EB1
	J. 200	120: Fault on 2nd EB1
	off.	210: Fault on 1st EB2
		220: Fault on 2nd EB2
F073	4 mA at analog input 1, slave 1 fallen short of	Check the connection of the signal source to
	7.0	the SCI1 (slave 1) -X428: 4, 5.
AnInp1SL1	The state of the s	The same of the sa
2/1	27,	27,
not Compact PLUS		
F074	4 mA at analog input 2, slave 1 fallen short of	Check the connection of the signal source to
	8.	the SCI1 (slave 1) -X428: 7, 8.
AnInp2 SL1	The The	The The
)	
not Compact PLUS	-05	· OL.
F075	4 mA at analog input 3, slave 1 fallen short of	Check the connection of the signal source to
	. XC	the SCI1 (slave 1) -X428: 10, 11.
AnInp3 SL1	45	45
	The state of the s	The state of the s
not Compact PLUS	2,	10
F076	4 mA at analog input 1, slave 2 fallen short of	Check the connection of the signal source to
	A	the SCI1 (slave 2) -X428: 4, 5.
AnInp1 SL2	18 N	7.9%
	the safe	A. A.
not Compact PLUS 🦯	A COLUMN TO THE PARTY OF THE PA	The state of the s
F077	4 mA at analog input 2, slave 2 fallen short of	Check the connection of the signal source to
	200	the SCI1 (slave 2) -X428: 7, 8.
AnInp2 SL2	190	, , , , , , , , , , , , , , , , , , , ,
47	2/1	M.
not Compact PLUS	74,	.47
F078	4 mA at analog input 3, slave 2 fallen short of	Check the connection of the signal source to
	. ,	the SCI1 (slave 2) -X428: 10, 11.
AnInp3 SL2	9	9
	10×	70 x
not Compact PLUS	1625	"A), "A),
F079	No telegram has been received by the SCB	- Check the connections of the SCB1(2).
10	(USS, peer-to-peer, SCI) within the telegram	10,
SCB telegram failure	failure time.	- Check P704.03"SCom/SCB Tlg OFF"
CCD tologiain landio		Check 1 104.00 Goodily God Tig Of 1
not Compact PLUS	My. My	- Replace SCB1(2)
not compact Loc	The Tay	1.05,000 005 1(2)
		- Replace CU (-A10)
	The state of the s	11001000 00 1 / 110/

Number / Fault	Cause	Counter-measure
F080	Fault during initialization of the board at the	Fault value r949:
TB/CB initialization	DPR interface	1: Board code incorrect
fault		2: TB/CB board not compatible 3: CB board not compatible
lauit	2	5: Error in configuration data
	(%),	6: Initialization timeout
	TO 30	7: TB/CB board double
		10: Channel error
	760.	Charletha T200/CD hazard for accurate
	X0 ⁰⁰ X0	Check the T300/CB board for correct contacting and check the CB initialization
	24.	parameter:
	74,	- P918.01 CB Bus Address,
4	4	- P711.01 to P721.01 CB parameters 1 to 11
F081	Heartbeat-counter of the optional board is no	Fault value r949:
OptBrdHeartbeat-	longer being processed	0: TB/CB heatbeat-counter 1: SCB heartbeat-counter
Counter	The state of the s	2: Additional CB heartbeat-counter
Counter		2. Additional OB ricartocal counter
	10	- Acknowledge the fault (whereby automatic
	2000	reset is carried out)
	7,0,	- If the fault re-occurs, replace the board
	The Think	concerned (see fault value)
	2, 2,	- Replace ADB - Check the connection between the subrack
		and the optional boards (LBA) and replace, if
	3	necessary
F082	No new process data have been received by	Fault value r949:
TD (0D) 1 (11)	the TB or the CB within the telegram failure	1 = TB/CB
TB/CB telegram failure	time.	2 = additional CB
	7.00 X	- Check the connection to TB/CB
		- Grieck the connection to 1 b/Gb
	Phys.	- Check P722 (CB/TB TlgOFF)
	3, 3,	77, 3
		- Replace CB or TB
F085	A fault has occurred during initialization of the CB board.	Fault value r949:
Add. CB initialization	CB board.	1: Board code incorrect 2: TB/CB board not compatible
fault	7.50	3: CB board not compatible
	*OC.	5: Error in configuration data
	7.00°	6: Initialization timeout
	(d).	7: TB/CB board double
	Ty.	10: Channel error
	72, 72,	Check the T300 / CB board for correct
		contacting and check the CB initialization
	9	parameters:
	TOX NOX	- P918.02 CB Bus Address,
F007	A 6 16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- P711.02 to P721.02 CB Parameters 1 to 11
F087	A fault has occurred during initialization of the	- Replace CU
SIMOLINK initialization	SLB board.	- Replace SLB
fault	38.	TOPIGOO OLD
F114	The converter has automatically stopped the	Re-start with P115 function selection = 2
	automatic measurement due to the time limit	"Motor identification at standstill". The ON
MId OFF	up to power-up having been exceeded or due	command must be given within 20 sec. after
	to an OFF command during the measurement,	the alarm message A078 = standstill
	and has reset the function selection in P115.	measurement has appeared.
	762.	Cancel the OFF command and re-start
	76/2	measurement.
F116	See TB documentation	See TB documentation
7.72	,X) ^{6*} ,X	, YO _O
Technology board fault	''''.	
not Compact DLUC	24, 24,	The state of the s
not Compact PLUS	1, 1,	7, 7

Number / Fault	Cause		Counter-measure	,
F117	See TB documentation		See TB documentation	
Technology board fault	200		20,	
F118	See TB documentation		See TB documentation	
Tachnology board foult	9		9	
Technology board fault	The state of the s		The.	
not Compact PLUS 🧢			Car.	Car.
F119	See TB documentation		See TB documentation	
Technology board fault	. 80°		, , , , , , , , , , , , , , , , , , , ,	
12/1	and the		747	
not Compact PLUS F120	See TB documentation	The same	See TB documentation	
F120	See 16 documentation		See 16 documentation	
Technology board fault	3		200	
not Compact PLUS	the The		"The	
F121	See TB documentation		See TB documentation	- 10°
	Tigo.		160.	
Technology board fault	1900		(1)	
not Compact PLUS	"My"		"This	
F122	See TB documentation	24,	See TB documentation	
Technology board fault				
Technology board raun	3		20	
not Compact PLUS	The The		The.	The
F123	See TB documentation		See TB documentation	
Technology board fault	Nigo.		20.	
900	1900		, '92,	
not Compact PLUS F124	See TB documentation	- 44,	See TB documentation	
1124	See 1B documentation		See 1B documentation	
Technology board fault				
not Compact PLUS	23		, <u>(</u>)	
F125	See TB documentation		See TB documentation	201
Ta alama la mulha and fault	- Allio		Olive .	
Technology board fault			120°	
not Compact PLUS	.87	96,	(9)	
F126	See TB documentation		See TB documentation	
Technology board fault	2,		2,	
not Compact PLUS F127	See TB documentation		See TB documentation	7.00
121	See 1B documentation		See 15 documentation	
Technology board fault	"Office		"O(C)	
not Compact PLUS	~allie		Z ₂ ~3	
F128	See TB documentation	- (6)	See TB documentation	
- 12 Mar.	" May		"Aza,	
Technology board fault	2,		27	
not Compact PLUS	2		2	_
F129	See TB documentation		See TB documentation	73.5
Technology board fault	3, 124,		247	
. cominional board rault	, of C.		xoff.	
not Compact PLUS	0 70 1		O TD I	2.
F130	See TB documentation		See TB documentation	
Technology board fault	"Inter-		'41 ₂₁ ,	
	2.		24	
not Compact PLUS				

Number / Fault	Cause	20	Counter-measure	ǰ
F131	See TB documentation	71/0	See TB documentation	,
- The	TH.		744	
Technology board fault	4		-20	
not Compact PLUS				
F132	See TB documentation		See TB documentation	
	goo . 2 doododa.		200 12 0000	
Technology board fault	· Carrie		-420m	
	"Ago,		20.	
not Compact PLUS F133	See TB documentation		See TB documentation	Ş ⁰ ~~~~
1133	See 1B documentation		See 15 documentation	
Technology board fault	The same of the sa		267	
not Compact PLUS	2 75 1		0 70 1	
F134	See TB documentation		See TB documentation	
Technology board fault	100		A. C.	
	ACC CONTRACTOR OF THE PROPERTY		allie	
not Compact PLUS	30,		30.	20.
F135	See TB documentation		See TB documentation	
Technology board fault	24. C		41/	
recrinology board rault	The state of the s		2627	
not Compact PLUS				
F136	See TB documentation		See TB documentation	2
	195.		13.2	
Technology board fault	100		TO THE	
not Compact PLUS	ALC.		alle	
F137	See TB documentation		See TB documentation	2010
	.800		6.	
Technology board fault	"Ay		14/1	
not Compact PLUS	The same of the sa		Mr.	
F138	See TB documentation		See TB documentation	
9	9		9	
Technology board fault	10×		10.7	
not Compact DLUC	l, "35),		20,	
not Compact PLUS F139	See TB documentation		See TB documentation	*0,47,
1 100	Geo 12 documentation		Occ 1B documentation	
Technology board fault	.60			
	Ty.		The state of the s	
not Compact PLUS F140	See TB documentation	7/2	See TB documentation	
F140	See 16 documentation		See 16 documentation	
Technology board fault	6 6		9	
	to.,		Mo.	
not Compact PLUS			20	700
F141	See TB documentation		See TB documentation	
Technology board fault	~90°		D.	
. somology board rault	(4)		(4)	
not Compact PLUS	The state of the s	The same	77/1/4	
F142	See TB documentation		See TB documentation	
Tachnology board facilit				
Technology board fault	6.		9	
not Compact PLUS	Fr. "Mar.		Tho.	
F143	See TB documentation		See TB documentation	No.
	200		10,	
Lechnology board fault	N.			
Technology board fault	70,0		V	

Number / Fault	Cause	Counter-measure
F144	See TB documentation	See TB documentation
	The The	and the same of th
Technology board fault	4.	4.
not Compact PLUS	A	
F145	See TB documentation	See TB documentation
X	100	19 ¹
Technology board fault	Allico .	ALLEO ALLEO
not Compact DLUS	"Tigo.	"Tip.
not Compact PLUS F146	See TB documentation	See TB documentation
1140	See 1B documentation	See 1B documentation
Technology board fault	742,	
3,	1, 1,	2, 2
not Compact PLUS		
F147	See TB documentation	See TB documentation
	to.	To.
Technology board fault	, XVII.	790
not Compact DLUC	, o ^C	x0°
not Compact PLUS F148	An active signal is present at binector U061	Examine cause of fault, see function diagram
Г140	(1).	710
Fault 1	(1).	710
Function blocks	The The	77, 7
F149	An active signal is present at binector U062	Examine cause of fault, see function diagram
	(1).	710
Fault 2	1987	25,
Function blocks	The state of the s	The same
F150	An active signal (1) is present at binector	Examine cause of fault, see function diagram
Fault 0	U063.	710
Fault 3 Function blocks	25 M	A
F151	An active signal is present at binector U064	Examine cause of fault, see function diagram
1 101	(1).	710
Fault 4	(1).	110
Function blocks		
F255	A fault has occurred in the EEPROM.	Switch off the unit and switch it on again. If the
	70x	fault re-occurs, replace the CU.
Fault in EEPROM	1° 29'	10° (Dr.

Table 12-1 Fault numbers, causes and their counter-measures

12.2 Alarms

The alarm message is periodically displayed on the PMU by A = alarm/ alarm message and a 3-digit number. An alarm cannot be acknowledged. It is automatically deleted once the cause has been eliminated. Several alarms can be present. The alarms are then displayed one after the other.

When the converter is operated with the OP1S operator control panel, the alarm is indicated in the lowest operating display line. The red LED additionally flashes (refer to the OP1S operating instructions).

Cause	Counter-measure
The computing time work load is too high	- Reduce pulse frequency
, itorrates	- Calculate individual function blocks in slower time slots (parameter U950 ff.)
Start of the SIMOLINK ring is not functioning.	- Check the fiber-optic cable ring for
"(O. "TO.	interruptions
May May	- Check whether there is an SLB without voltage in the ring
16.1g	- Check whether there is a faulty SLB in the ring
Although synchronization has been activated,	SIMOLINK (SLB):
	- Check r748 i002 and i003 = counters for
	CRC faults and timeout faults - Check the fiber-optic cable connection
	- Check P751 on the dispatcher (connector
	260 must be softwired); Check P753 on the
cycle times or synchronization of slow time	transceiver (corresponding SIMOLINK
	connector K70xx must be softwired).
	9
	160,
The DC link voltage is not equal to 0 when the	- Set P372 to 0.
simulation mode is selected (P372 = 1).	10x
12/ _{12/2} 14/ ₂	- Reduce DC link voltage (disconnect the converter from the supply)
Parameterizable external alarm input 1 has	Check
been activated.	whather the cable to the corresponding
	whether the cable to the corresponding digital input has been interrupted.
2	digital input has been interrupted.
10×	- parameter P588 Src No Ext Warn1
Parameterizable external alarm input 2 has	Check
been activated.	
, Jin	- whether the cable to the corresponding
'95 ₀ , '95 ₀	digital input has been interrupted.
all	- parameter P588 Src No Ext Warn2
SAFE OFF is detected in the READY states.	See F017 for causes/counter-measures.
\$. \$	6
Signal amplitude	See F051 for causes/counter-measures.
Resolver/encoder in the critical range.	The Thin
Connection fault of the serial protocol on	Serial protocol is defective on multiturn encoders. See F051 for causes/counter-
munitum encoders (551/Endat)	measures.
	The computing time work load is too high Start of the SIMOLINK ring is not functioning. Although synchronization has been activated, the drive is not synchronous. Possible causes are: - Poor communication connection (frequent telegram failures) - Slow bus cycle times (in the case of high bus cycle times or synchronization of slow time slots, synchronizing can last for 1-2 minutes in the worst case). - Incorrect wiring of the time counter (only if P754 > P746 /T0) The DC link voltage is not equal to 0 when the simulation mode is selected (P372 = 1). Parameterizable external alarm input 1 has been activated. Parameterizable external alarm input 2 has been activated.

Number / Alarm	Cause	Counter-measure
A022	The threshold for tripping an alarm has been	- Measure intake air and ambient temperature.
22/2	exceeded.	
Inverter temperature		- Observe derating curves at q > 50°C (Compact PLUS) or 40°C
	10.th	- Check whether the fan is operating
	ed.	- Check whether the air entry and discharge
A000	The peremeterizable threshold (D200) for	openings are restricted. Check the motor (load, ventilation, etc.). Read
A023	The parameterizable threshold (P380) for tripping an alarm has been exceeded.	off the current temperature in r009 Motor Temperat.
Motor temperature A024	If the current load state is maintained, a	- Reduce converter load
12t converter	thermal overload of the converter occurs.	- Check r010 (Drive Utiliz)
12t conventer	The converter will lower the max. current limit limit (P129).	Official To To (Brive Guill2)
A029	The parameterized limit value for the I2t	Motor load cycle is exceeded!
IOL markers	monitoring of the motor has been exceeded.	Charletha manageratana
I2t motor	7.00 T	Check the parameters:
	(b).	P382 Motor Cooling
	The state of the s	P383 Mot Tmp T1
1022	The positive or posetive maximum around has	P384 Mot Load Limits
A033 Overspeed	The positive or negative maximum speed has been exceeded.	- Increase relevant maximum speed - Reduce regenerative load (see FD 480)
A034	Bit 8 in r552 status word 1 of the setpoint	Check
71001	channel. The difference between frequency	OHOSK!
Setpoint/actual value deviation	setpoint/actual value is greater than the parameterized value and the control	- whether an excessive torque requirement is present
	monitoring time has elapsed.	- whether the motor has been dimensioned too
	Hy.	small.
A036	The brake checkback indicates the "Brake still	Increase values P792 Perm Deviation Frq/set/actual DevSpeed and P794 Deviation Time Check brake checkback (see FD 470)
ă.	closed" state.	Check brake checkback (see FD 470)
Brake checkback "Brake still closed"	"OUL	"OLL"
A037	The brake checkback indicates the "Brake still open" state.	Check brake checkback (see FD 470)
Brake checkback	Ty.	My.
"Brake still open" A042	Motor is stalled or blocked.	Check
A042		Check
Motor stall/lock	The alarm cannot be influenced by P805 "PullOut/BlckTime", but by P794 "Deviation	- whether the drive is locked
, a s	Time"	- Whether the drive has stalled
A049	At serial I/O (SCB1 with SCI1/2), no slave is connected or fiber-optic cable is interrupted or	P690 SSCI Analn Conf
No slave	slaves are without voltage.	- Check slave.
not Compact PLUS	"uy." "uy.	- Check cable.
A050	At ser. I/O the slaves required according to a	Check parameter P693 (analog outputs), P698
Slave incorrect	parameterized configuration are not present (slave number or slave type): Analog inputs or	(digital outputs). Check connectors K4101K4103, K4201K4203 (analog inputs)
not Compact PLUS	outputs or digital inputs or outputs have been parameterized which are not physically	and binectors B4100B4115, B4120B4135, B4200B4215, B4220B4235 (digital inputs)
A051	present.	for connecting.
A051	In a peer-to-peer connection a baud rate has been selected which is too high or too	Adjust the baud rate in conjunction with the SCB boards P701 SCom/SCB Baud Rate
Peer baud rate	different.	770,

Number / Alarm	Cause	Counter-measure
A052	In a peer-to-peer connection, a PcD length has	Reduce number of words P703 SCom/SCB
22/2	been set which is too high (>5).	PcD#
Peer PcD L	2. 2.	200
in a t Common a a t DI LIC		
not Compact PLUS A053	In a peer-to-peer connection, the pcD length of	Adjust the word length for transmitter and
A000	transmitter and receiver do not match.	receiver
Peer Lng f.	transmitter and receiver do not materi.	P703 SCom/SCB PcD #
,	202	XQL
not Compact PLUS		7.872
A057	Occurs when a TB is logged on and present,	Replace TB configuration (software)
TD Dames Mark	but parameter tasks from the PMU, SCom1 or	71/24.
TB Param	SCom2 have not been answered by the TB within 6 seconds.	37, 3
not Compact PLUS	Within 0 Seconds.	
A061	An active signal is present at binector U065	Check cause of alarm (see FD 710)
X.00.	(1).	Chosh cause of alami (coo i 2 i io)
Alarm 1	100	19,
Function blocks		all's all's
A062	An active signal is present at binector U066	Check cause of alarm (see FD 710)
Alorm 2	(1).	'92 ₀ ,
Alarm 2 Function blocks	'M'.	W.
A063	An active signal is present at binector U067	Check cause of alarm (see FD 710)
	(1).	553K 64465 5F 414111 (556 F 5 F 10)
Alarm 3		
Function blocks	20,	2,0
A064	An active signal is present at binector U068	Check cause of alarm (see FD 710)
	(1).	Man, Man,
Alarm 4 Function blocks	. 10°	10°
A075	The measured values of the leakage	If individual measured values significantly
A075	measurement or of rotor resistance deviate	deviate from the average values, they are
Thu.	significantly.	automatically not taken into account for the
10	, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	calculation (for RI) or the value of the
		automatic parameterization remains (for Ls).
d)	9	It is only necessary to check the results for
	Fo.,	their plausibility in the case of drives with high requirements on torque or speed accuracy.
A078	The standstill measurement is executed when	If the standstill measurement can be executed
71070	the converter is powered up. The motor can	without any danger:
Stands. Meas	align itself several times in a certain direction	,,,gan
(d)	with this measurement.	- Power up the converter.
A081	See user manual for CB board	My.
00.1	74, 74,	72,
CB alarm	See user manual for CB board	
A082	See user manual for CB board	9
CB alarm	TOX NO.X	70x
A083	See user manual for CB board	100
- office	-8E-	-0/L
CB alarm	"ZE, "	25.
A084	See user manual for CB board	'92 ₀ ,
CB alarm	Mr. William	.44.5
A085	See user manual for CB board	20%
7,000	occ user mandar for ob board	
CB alarm	2	
A086	See user manual for CB board	79%
	76	1/2. This
	1, 20	-60
AU8/	See user manual for CB board	20. "20.
CR alarm	20% 20%	100°
	See user manual for CB board	77.0.
,1000	See addi manda for OB board	"zt"
CB alarm	2, 2,	47
A086 CB alarm A087 CB alarm A088	See user manual for CB board See user manual for CB board See user manual for CB board	Mary applicately or in the state of the stat

Number / Alarm	Cause	Counter-measure
A089	See user manual for CB board	
00 1 200	Alarm of the 2nd CB board corresponds to	And the state of t
CB alarm	A81 of the 1st CB board	
A090	See user manual for CB board Alarm of the 2nd CB board corresponds to	
CB alarm	A82 of the 1st CB board	'S, 'S,
A091	See user manual for CB board	13/1
- 100 I	Alarm of the 2nd CB board corresponds to	
CB alarm	A83 of the 1st CB board	⁷ 0,
A092	See user manual for CB board	731 Z
(O)	Alarm of the 2nd CB board corresponds to	
CB alarm	A84 of the 1st CB board	
A093	See user manual for CB board Alarm of the 2nd CB board corresponds to	37, 3
CB alarm	A85 of the 1st CB board	
A094	See user manual for CB board	9, 9,
	Alarm of the 2nd CB board corresponds to	13,2
CB alarm	A86 of the 1st CB board	'20,
A095	See user manual for CB board	.0 ^[1]
and the same	Alarm of the 2nd CB board corresponds to	
CB alarm	A87 of the 1st CB board	'90,
A096	See user manual for CB board Alarm of the 2nd CB board corresponds to	The state of the s
CB alarm	A88 of the 1st CB board	74,
A097	See user manual for TB board	
2	à à	
TB alarm 1	198,	7.9%
	The same of the sa	16 16 16 16 16 16 16 16 16 16 16 16 16 1
not Compact PLUS		
A098	See user manual for TB board	20,
TB alarm 1	70 ⁵⁰	20 ²
TD alailli T	450	(A)
not Compact PLUS	747.	The state of the s
A099	See user manual for TB board	
TB alarm 1	"S,	"Z), "Z),
not Compact PLUS	The "The	The The
A100	See user manual for TB board	
71100	See assi manda for 12 source	² O ₁ , ² O ₁ ,
TB alarm 1	18 m	- 54 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5
770	360	
not Compact PLUS	- "Ly," - " " " " " " " " " " " " " " " " " "	
A101	See user manual for TB board	7, 3
TB alarm 1		
alailii i	9	9
not Compact PLUS	to.	W.
A102	See user manual for TB board	790
"Office	"QL.	.00
TB alarm 1	- Allie	The state of the s
not Compact DLUC	(S)	(6)
not Compact PLUS A103	See user manual for TB board	
V102	See user manual for 10 board	Mr. I
TB alarm 1		
À	A	
not Compact PLUS	.a ²	, o.X
A104	See user manual for TB board	76° 26°
TD alams 4	"(C _i o	This This
TB alarm 1	"Z _C .	$Z_{C_{i}}$
not Compact PLUS	70 ₀₀ ,	70 ₀
not Compact LOC	.59	<u> </u>

Number / Alarm	Cause	20,	Counter-measure	
A105	See user manual for TB board	This.	"77;	
TD 1 254	Sep.	42,		
TB alarm 1	-	4.		
not Compact PLUS				
A106	See user manual for TB board			- 8
A100	See user manual for 15 board			
TB alarm 1	y, , , , , , , , , , , , , , , , , , ,			
	10°	2		
not Compact PLUS	~8 ²	S	× × × × × × × × × × × × × × × × × × ×	
A107	See user manual for TB board	. (0)		
TD alamas	The state of the s	44.		
TB alarm 1	The same of the sa	2/2		
not Compact PLUS				
A108	See user manual for TB board			
7100	occ user manual for 15 board			
TB alarm 1	10			
	, and the second			
not Compact PLUS	76	3	10	
A109	See user manual for TB board	30%		
TD alama 4		74,00		
TB alarm 1	THE.	11/2		
not Compact PLUS	2.	2		
A110	See user manual for TB board			
NI IO	occ aser manda for 12 board			
TB alarm 1	Ko.			
not Compact PLUS	"o _C "		.05	
A111	See user manual for TB board			
	1,00	(20)		
TB alarm 1	247	127.		
not Compact DLUC	The state of the s	27,20		
not Compact PLUS A112	See user manual for TB board			
A112	See user manual for 15 board			
TB alarm 1	"85.			
	10 M			
not Compact PLUS	,		Z.O	
A113	See user manual for TB board	3		
TD alama 0	3000	300		
TB alarm 2	77,0	7.60		
not Compact PLUS	"The	14/10.		
A114	See user manual for TB board	- 17		
TB alarm 2	6			
	To.,			
not Compact PLUS	2)		790	
A115	See user manual for TB board			
TP clorm 2	- 8171	_0.5		
TB alarm 2	,3°C	.66		
not Compact PLUS	24/2	Ty.		
A116	See user manual for TB board	21,00	144	7
-				
TB alarm 2	2			
8.	[42]			
not Compact PLUS	12. M.			~
A117	See user manual for TB board			
TP clarm 2	70	3		
TB alarm 2	70g/	303		
not Compact PLUS	760,	160,		
not Compact I LOC		- 623		

Number / Alarm	Cause	Counter-measure
A118	See user manual for TB board	74.C
TD -1	May, May	, 10 May 3
TB alarm 2		
not Compact PLUS		
A119	See user manual for TB board	79%
TD -laws 0	A. A	ight and ight
TB alarm 2	"Office	10 CC
not Compact PLUS		
A120	See user manual for TB board	.0
TB alarm 2	May.	144.
ID didilii Z	2, 2,	27, 3
not Compact PLUS		
A121	See user manual for TB board	3
TB alarm 2	the "The	The The
ID didiiii Z	Contract of the contract of th	Ton,
not Compact PLUS	70,	10,
A122	See user manual for TB board	.X5°
TB alarm 2	M. C.	
1D didilii Z	The Think	, 2 ₁₂ , 3
not Compact PLUS		
A123	See user manual for TB board	20 20 20
TB alarm 2	10 x	10,4
TD didiffi 2	9.	'80,
not Compact PLUS	.0[1	-off,
A124	See user manual for TB board	7.32.
TB alarm 2	30	
1B didiiii E	Ar. A	Ta.
not Compact PLUS	2, 2,	1, 1
A125	See user manual for TB board	
TB alarm 2	. AS'	2
	The second	19 ¹
not Compact PLUS	On a second for TR hand	- Mic
A126	See user manual for TB board	
TB alarm 2	1900	. 35°
747	and it	The state of the s
not Compact PLUS	See user manual for TB board	- 1 ₂₄ - 1
A127	See user manual for 1B board	
TB alarm 2	6	6.
)**	K.,	The.
not Compact PLUS A128	See user manual for TB board	
A120	See user manual for TD board	40,
TB alarm 2	20 ²⁰	70gr.
not 0 mn of DLU0	M. S.	M.O.
not Compact PLUS A129	Machine data 1 (position encoder type/ax	is You must assign a valid value to machine data
71120	type) is 0 (axis does not exist).	1 in order to operate the axis.
Axis does not exist -	à à	2
machine data 1 = 0	Effect:	79%
ă.	Operation of the axis is inhibited and the position controller is deactivated.	19 ¹
	position controller is deactivated.	20

Number / Alarm	Cause	Counter-measure
A130	The "in operation" [IOP] checkback signal was	Activate control signals [OFF1], [OFF2],
	missing when a traversing command was	[OFF3] and "enable controller" [ENC].
Operating conditions	initiated. The following causes inhibit the "in	2,
do not exist	operation" checkback signal (status bit No.2,	-If checkback signals [OFF2] and/or [OFF3]
	refer to function diagram sheet 200):	are missing, check the supply of control word
	1.0 ^N	1 (MASTERDRIVE function diagram, sheet
	-Control signals [OFF1], [OFF2], [OFF3]	180).
	and/or "enable controller" [ENC] are not	The state of the s
	activated.	-Analyze the gueued fault number
	all the second s	[FAULT_NO], remedy the fault, and then
	-Checkback signals [OFF2] and/or [OFF3] are	cancel the fault using the acknowledge fault
	not activated.	[ACK_F] control signal.
	777	1 = 1
	-A fault [FAULT] is active.	Note:
		To activate the "in operation" [IOP] status
	Effect:	again, you must deactivate [OFF1] and then
	The traversing command is inhibited.	activate it again.
A131	Control signal [OFF1] was deactivated while a	Check the activation of control signal [OFF1]
	traversing command was being executed.	from the user program.
OFF1 missing		10,
	Effect:	× × × × × × × × × × × × × × × × × × ×
	The drive is brought to a standstill via a ramp	(5)
	(machine data 43: deceleration time during	a_{j} .
	faults). There is a subsequent pulse disable.	The state of the s
A132	-Control signal [OFF2] was deactivated while a	-Check the activation of control signal [OFF2]
1102	traversing command was being executed.	from the user program.
OFF2 missing	travoroning communia was being exceuted.	nom the door program.
5112111100111g	-Checkback signal [OFF2] was deactivated	-If checkback signal [OFF2] is missing, check
	while a traversing command was being	the supply of control word 1 (MASTERDRIVE
	executed.	function diagram, sheet 180).
	excoured.	Tariotion diagram, shoct 100).
	Effect:	Note:
	The pulse disable is initiated immediately. If	To activate the "in operation" [IOP] status
	the motor is not braked, it coasts down.	again, you must deactivate [OFF1] and then
	the motor is not branca, it escape down.	activate it again.
A133	-Control signal [OFF3] was deactivated while a	-Check the activation of control signal [OFF3]
1100	traversing command was being executed.	from the user program.
OFF3 missing	travoroning communia was being exceuted.	nom the door program.
Of the fillioning	-Checkback signal [OFF3] was deactivated	-If checkback signal [OFF3] is missing, check
	while a traversing command was being	the supply of control word 1 (MASTERDRIVE
	executed.	function diagram, sheet 180).
	oxecuted.	Tariotion diagram, ondoc 100).
	Effect:	Note:
	The motor decelerates at the current limit.	To activate the "in operation" [IOP] status
	There is a subsequent pulse disable.	again, you must deactivate [OFF1] and then
	io a dabodquoin puloo dibabio.	activate it again.
A134	The "enable controller" [ENC] control signal	Check the activation of the "enable controller"
, 110 1	was deactivated while a traversing command	[ENC] control signal from the user program.
Enable Controller ENC	was being executed (control bit No.3 "Inverter	[2110] control signal from the user program.
missing	Enable", refer to function diagram, sheet 180)	The The
509	=abio , rotor to ranotion diagram, bricet 100)	The,
	Effect:	*Q
	The pulse disable is initiated immediately. If	Dr. Wille
	the motor is not braked, it coasts down.	'95.
A135	Actual position value not o.k. from position	-Check interconnection of B0070 and B0071,
	sensing (B0070 / B0071)	-check position encoder and evaluation board
Actual position value	Conding (Door o / Door 1)	-check encoder cable.
not o.k		SHOOK GHOOGGI GADIG.
	Machine data 1 (position aneador type/axis	If machine data 1 has been shanged the
A136	Machine data 1 (position encoder type/axis	If machine data 1 has been changed, the
Machina data 4	type) was changed.	"reset technology" [RST] control signal must
Machine data 1	Effort	be activated. Alternatively switch the
changed - RESET	Effect:	MASTERDIVES electronic power supply off
necessary	The activation of traversing commands is	and on again
	inhibited.	207

Number / Alarm	Cause	Counter-measure
A137 Axis assignment	The same axis assignment (machine data 2) was entered for several axes (M7 only, not significant for the F01 technology option).	A unique axis assignment must be entered for all axes on an M7-FM. For example, it is not allowed to define two X axes.
incorrect		
	Effect:	9, 9,
	The activation of traversing commands is inhibited.	16°
A138	The NC block contains an axis number which	-Axis type 1 or 2:The block is not allowed to
Axis assignment of roll feed incorrect	is defined as a roll feed axis but the axis type is defined as an incremental or absolute position encoder (machine data 1 = 1 or 2). (M7 only, not significant for the F01 technology option).	contain an axis number which is defined as a roll feed (M7 only). -Axis type 3:The axis number of the roll feed must be specified in every NC block.
	The NC block for a roll feed axis type (machine data 1 = 3) contains: -No axis number (X, Y, Z) -An incorrect axis number	must be specified in every No block.
	Effect:	*0C,
~9 ₁₁	NC program execution is inhibited or aborted.	7. "A)
A140	The following error limit for standstill was	-Check and correct the machine data.
	exceeded at standstill:	Hy.
Following error in	72, 72,	-Optimize the speed/current controller,
standstill	-Following error monitoring - at standstill	Death and a charles and a second
	(machine data 14) was entered incorrectly.	-Rectify mechanical problem.
	-The value entered for "in position - exact stop	70%
	window" (machine data 17) is greater than the	Vigg,
	value in "following error monitoring - at standstill" (machine data 14).	Roll,
	-The axis was pushed out of position	7/2
	mechanically.	Har.
	Effect:	
	The position control system is deactivated and the axis decelerates via "deceleration time	70/3
A141	during errors" (machine data 43). The following error limit for motion was	-Check and correct the machine data.
.017	exceeded during a traversing movement:	Shock and correct the machine data.
Following error in		-Optimize the position controller or the speed
motion	-Following error monitoring - in motion (machine data 15) was entered incorrectly.	controller.
	- 2 ₁₂	-Check the mechanical system.
	-The mechanical system cannot follow the commands of the position controller.	
	-Incorrect optimization of the position controller	'S,
	or speed controller.	-19th
	-The mechanical system is sluggish or blocked.	JOPPE HOPE
	(0)	(0)
	Effect:	$H_{M_{p}}$.
	The position control system is deactivated and the drive decelerates via "deceleration time during faults" (machine data 43).	7, 7

Number / Alarm	Cause	Counter-measure
A142	The "in position - exact stop window" was not reached within the time specified in in position	-Check and correct the machine data.
In position - timer monitoring	- timer monitoring":	-Optimize the position controller or speed controller.
	-In position - exact stop window (machine data 17) too small	-Check the mechanical system.
	-In position - timer monitoring (machine data	190
	16) too short	HOPE SHOPE
	-Position controller or speed controller not optimized	"High,
	. The The	The state of the s
	-Mechanical causes	7
	Effect:	4.
	The position control system is deactivated.	NO.
A145	The "digital input" with the "disable actual value" function was actuated while the roll	The "digital input" for "disable actual value" can only be actuated when the axis is
Actual-value disable not allowed - axis	feed was running.	stationary.
tandstill	Effect:	, J.C.
	The axis movement is stopped via the	'Edy'
	deceleration ramp, the "disable actual value" function is not executed.	The s
146	A positioning movement was aborted. When	Move the axis in front of the target position in
	attempting to resume the movement at the	setup mode before continuing.
Direction of movement	point of interruption, the roll feed would have	:3/h
not allowed	had to travel in the opposite direction to reach the programmed target position. This is	Elg.,
	inhibited by the setting of machine data 37	10°
	"response after abort".	7 30 ²
	. " _(Q)	770,
	There are various possible reasons for the axis crossing the target position when a positioning movement is aborted:	May.
	-Motor coastdown	(a)
	The evic was moved intentionally a g in	adt adt
	-The axis was moved intentionally, e.g. in setup mode.	tours, Tours
	Effect:	, 10 ²⁰
	The axis movement is inhibited.	250
1148	The current deceleration value is 0, e.g. because of a RAM storage error or an error in	This fault should not normally occur. It is used as an emergency stop feature for the
Deceleration = 0	the technology firmware.	technology software.
	9	Replace the hardware (M7; MCT).
	Effect:	16 x
	The position control system is deactivated and the drive is decelerated via the "deceleration"	190,
	time during errors" (machine data 43).	"QL
149	Internal error in the technology software.	This fault should not normally occur. It is used
92,		as an emergency stop feature for the
Distance to go negative	Effect:	technology software.
n.	The position control system is deactivated and the drive is decelerated via the "deceleration time during errors" (machine data 43).	Tr. 1

Number / Alarm	Cause	Counter-measure
A150	The selected NC program contains a slave	The same slave axis cannot be used
	axis which is already being used by another	simultaneously by several NC programs.
Slave axis already	master axis (M7 only, not significant for the	7, 7
allocated to other	F01 technology option).	
master axis	9	9
	Example:	7.6%
	NC program 1, started in axis X, contains NC	April 1997
	blocks for axes X and Y. NC program 2 is	Ton.
	started in axis Z and contains NC blocks for	(O)
	axes Z and Y. This program is denied with	7.95
	warning 150, because axis Y is already being	(3)
	used by program 1.	24,
	The state of the s	EL.
	Effect:	
	NC program execution is inhibited or aborted.	
A151	The slave axis required by the master axis is	The slave axis must be switched to "slave"
	not in "slave" mode (M7 only, not significant	mode.
Slave axis operating 🦼	for the F01 technology option).	"(2),
mode not allowed	"The	The Thirty
	Effect:	10.
	NC program execution is inhibited or aborted,	, x ₂
	the axis is brought to a standstill via the	(Q)
724.	deceleration ramp.	72,
A152	The "slave" mode was deselected in the slave	The slave axis must remain switched to
	axis during the traversing movement (M7 only,	"slave" mode.
Slave axis operating	not significant for the F01 technology option).	
mode changed	3	3,
-	Effect:	Mo.
	NC program execution is inhibited or aborted,	790
	the axis is brought to a standstill via the	Office Office
	deceleration ramp.	The state of the s
A153	A warning is active in the slave axis required	The NC program will only run if all of the axes
	by the master axis (M7 only, not significant for	it needs are error-free. To clear this warning,
Error in slave axis	the F01 technology option).	you must first clear all the warnings in the
	4,	slave axis.
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	The Sh
A154	The "follow-up mode" [FUM] control signal is	Deactivate follow-up mode in the slave axis.
	active in the slave axis required by the master	70x
Follow-up mode in	axis. A slave axis which is switched to follow-	2.
slave axis active	up mode cannot be operated by the master	.82
	axis (M7 only, not significant for the F01	24). T
	technology option).	
	-0.	A
	Effect:	
	NC program execution is inhibited or aborted,	9
	the axis is brought to a standstill via the	70 x
	deceleration ramp.	7/25
A155	The "reset" [RST] control signal is active in the	Cancel the "reset" [RST] control signal in the
	slave axis required by the master axis. A slave	slave axis.
Reset in slave axis	axis with an active reset cannot be used by the	
active	master axis (M7 only, not significant for the	(4)
	F01 technology option.	724.
	N. N.	77,
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	(6. (7.)
	deceleration ramp.	10.,

Number / Alarm	Cause	Counter-measure
A156	An NC program was started in which a slave	Axes defined as roll feed axes can only be
The same	axis is defined as a roll feed axis type (M7	used in dedicated NC programs.
Axis type (MD1) of	only, not significant for the F01 technology	
slave axis not allowed	option).	
	The warning is output in the master axis and	28
	indicates an illegal axis type in the slave axis.	"Ap.
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	My,
	Effect:	*0°C
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	,
	deceleration ramp.	.41.
A160	The value entered in level 1 or level 2 for the	Define a permissible velocity level for level 1
1.	[F_S] velocity level in setup mode is zero.	and/or level 2. The permissible value range is
Setup speed = 0	[= 1	between 0.01 [1000*LU/min] and "traversing
2011/2011	Effect:	velocity - maximum (machine data 23).
	The axis movement is inhibited.	10 X
A161	The velocity value entered for "reference point	Enter a permissible value for the approach
100	- approach velocity" (machine data 7) is zero.	velocity. The permissible value range is
Reference approach	1, 111,	between 0.01 [1000*LU/min] and "traversing
velocity = 0	Effect:	velocity - maximum (machine data 23).
	The axis movement is inhibited.	, , , , , , , , , , , , , , , , , , , ,
A162	The velocity value entered for "reference point	Enter a permissible value for the reference
21/4	- reducing velocity" (machine data 6) is zero.	point -reducing velocity. The permissible value
Reference point -	Todasing volosity (mashine data o) is zoro.	range is between 0.01 and 1000
reducing velocity = 0	Effect:	[1000*LU/min].
reading velocity = 0	The axis movement is inhibited or stopped.	[1000 20/11111].
A165	The MDI block number [MDI_NO] specified in	Define an MDI block number [MDI_NO]
A100	the control signals is greater than 11.	between 0 and 10.
MDI block number not	the control signals is greater than 11.	between o and ro.
allowed	Effect:	10.
allowed	The axis movement is inhibited.	S. S
A166	The "start" [STA] control signal was activated	Use the correct sequence: data transfer
A100	in MDI mode without initially transferring a	followed by axis start.
No position has been	positional value to the selected MDI block.	Tollowed by axis start.
programmed in MDI	positional value to the selected WD1 block.	
mode	Effect:	
X X	The axis movement is inhibited.	"S,
A167	The "start" [STA] control signal was activated	Use the correct sequence: data transfer
71107	in MDI mode without initially transferring a	followed by axis start.
No velocity has been	velocity value to the selected MDI block.	Tonomou by axio otan.
programmed in MDI	voidelty value to the colocied WET Blook.	Dr. Silver
mode	Effect:	,
do	The axis movement is inhibited.	'4' ₁₀
A168	G91 (incremental dimensions) was defined in	The MDI on-the-fly function only allows G90
11.00	the MDI block as the 1st G function for the	(absolute dimensions) as the 1st G function.
G91 not allowed with	MDI on-the-fly function.	
MDI on the fly		9
	Effect:	79×
	The axis movement is inhibited or stopped via	16.
	the deceleration ramp.	60
A169	-Control signal "reset technology" [RST]	Ensure that the control signals are activated
~35°	activated	correctly.
Start conditions for	(g)	
flying MDI do not exist	-Control signal "follow-up mode" [FUM]	12/1/2
,		120
	activated	-24
	activated	2,
		, ,
	Effect:	
A170	Effect: The "MDI on-the-fly" function is not executed.	Transfer the block
A170	Effect: The "MDI on-the-fly" function is not executed. An NC block was started in single-block mode	Transfer the block.
A170	Effect: The "MDI on-the-fly" function is not executed.	Transfer the block.
A170 Single block mode block does not exist	Effect: The "MDI on-the-fly" function is not executed. An NC block was started in single-block mode	Transfer the block.

Number / Alarm	Cause	Counter-measure
A172	The program number specified in [PROG_NO]	-Transfer the program to the technology.
Program with this	for automatic mode is not stored in the memory of the technology.	-Select the correct program number.
number does not exist		
	Effect:	9 9
A 4 7 0	NC program execution is inhibited.	The second secon
A173	The program number specified in [PROG_NO] for automatic mode is not allowed.	The permissible range for program numbers is between 1 and 200.
Program number not	for automatic mode is not allowed.	between 1 and 200.
allowed	Effect:	The State of the S
.35	NC program execution is inhibited.	180
A174	The program number [PROG_NO] was changed while the program was running.	The program number must not be changed while the program is running.
Program number		
changed during	Effect:	
traversing	NC program execution is aborted and the axis	3,
	or axes are brought to a standstill via the	The The
A 4.7F	deceleration ramp.	Course the black
A175	The decoded NC block is not terminated with the following block identifier "0".	Correct the block.
No block end	Variable was the Wayth of actual values	The last block in the sequence must contain
programmed	You can use the "output actual values - decoder error location" task to read out the	the following block identifier "0".
	program number and block number where the	"Ing.
	block decoder detected an error.	7.
	District district division division	
	Effect:	3
	NC program execution is inhibited or aborted.	The The
	Moving axes are stopped via the deceleration	The state of the s
	ramp.	-01
A177	The program number for the main program	Specify an existing main program number.
Prog. number of block	(level 0), which was transferred with the block search function, does not exist.	.67
search forwd. does not	Search function, does not exist.	724.
exist	Effect:	20, 7
	NC program execution is inhibited.	
A178	-The program number for the main program	For the block search function, the selected
	(level 0), which was transferred with block	program number [PROG_NO] must be
Program number of block search forward	search, is different from the selected program number.	specified as the program number for the main
not allowed	number.	program.
not allowed	-No breakpoint is known for the "automatic	70°
	block search" function (a program abort has	1,000
	not yet occurred).	
	The The	22/2
	-A different program number is stored as the	4.
	breakpoint for the "automatic block search"	
	function.	3
	Effect:	The The
	NC program execution is inhibited.	The state of the s
A179	The subprogram number specified with block	For the block search function, an existing
	search for level 1 or level 2 does not exist.	program number must be specified as the
Prog.No.of block srch	(d).	subprogram number for level 1 or level 2.
fwd level 1/2 does not	Effect:	The state of the s
exist	NC program execution is inhibited.	72,
A180	The subprogram number transferred with	For the block search function, the subprogram
Prog.no. of block	block search for level 1 is not the same as the	number specified in the NC block must be
search forward level 1	subprogram number in the NC block.	specified as the subprogram number for level 1.
<> cmd.	Effect:	" " " " " " " " " " " " " " " " " " "
ar oniu.	NC program execution is inhibited.	"Uio
A181	The subprogram number transferred with	For the block search function, the subprogram
700	block search for level 2 is not the same as the	number specified in the NC block must be
Prog.no. of block	subprogram number in the NC block.	specified as the subprogram number for level
search forward level 2		2.
<> cmd.	Effect:	-71
	NC program execution is inhibited.	

Number / Alarm	Cause	Counter-measure
A183	The block number for the main program (level 0), which was transferred with block search,	For the block search function, an existing block number must be specified as the block
Block no. of block search fwd I. 0 does	does not exist in the main program.	number for the main program.
not exist	Effect: NC program execution is inhibited.	300
A184 Block no. of block search forward is no UP call	The block number for the main program (level 0), which was transferred with block search, does not contain a subprogram call for subprogram level 1. Effect:	For the block search function, a block number with a subprogram call must be specified as the block number for the main program (level 0) if a block search is to be performed in subprogram level 1.
	NC program execution is inhibited.	All the second s
A185 Block no. of block search forward does not exist	The block number for subprogram level 1, which was transferred with block search, does not exist in the subprogram. Effect:	For the block search function, a block number which exists in this subprogram must be specified as the block number for subprogram level 1.
HOL EXIST	NC program execution is inhibited.	Tan,
A186 Block no of block search fwd level 1 is no UP call	The block number for subprogram level 1, which was transferred with block search, does not contain a subprogram call for subprogram level 2. Effect: NC program execution is inhibited.	For the block search function, a block number with a subprogram call must be specified as the block number for subprogram level 1 if a block search is to be performed in subprogram level 2.
A187 Block no. of block search forward does not exist	The block number for subprogram level 2, which was transferred with block search, does not exist in the subprogram. Effect: NC program execution is inhibited.	For the block search function, a block number which exists in this subprogram must be specified as the block number for subprogram level 2.
A188 Remaining no of loops block search fwd not allowed	The remaining loop count transferred with block search for subprogram level 1 or 2 is greater than the programmed loop count. Effect: NC program execution is inhibited.	For the block search function, it is only allowed to specify a remaining loop count between 0 and the programmed loop count-1.
A190 Digital input not programmed	The NC block which was read in contains the "inprocess measurement" or "set actual value on-the-fly" function, although a digital input has not been programmed for this function (machine data 45). Effect: NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	Program the digital input for the desired function.
A191	Although the "external block change" function	-Correct the program.
Digital input not actuated	was programmed, the digital input was not actuated in order to trigger the external block change.	-Check the actuation of the digital input.
MANATORIO	Effect: The NC program is interrupted, the axis is brought to a standstill via the deceleration ramp.	Aralia lilipo

Number / Alarm	Cause	Counter-measure
A195	-Negative software limit switch position approached	-Check the machine data and the NC program.
Negative overtravel	арргоаспеч	-Check the encoder actual value.
reached	-"Software limit switches - negative" (machine	Officer the chedder actual value.
Teached	data 12) entered incorrectly	
	action (2) contained incompany	75.
	-The programmed position is less than the	"A" "A"
	negative software limit switch.	Tar.
	x0\(\frac{1}{2}\)	70x
	-"Reference point - coordinate" (machine data	200 miles
	3) is less than the negative software limit	· (8)
	switch.	12/2
	21/2	774,
	-Incorrect encoder actual value	
	Effect:	200
	The axis movement is stopped via the	79×
	deceleration ramp.	161° 161°
A196	-Positive software limit switch position	-Check the machine data and the NC
	approached	programs.
Positive overtravel	2007	100 m
reached	-"Software limit switches - positive" (machine	-Check the encoder actual value.
	data 13) entered incorrectly"	The state of the s
	27, 27,	2h" 1
	-The programmed position is greater than the	
	positive software limit switch	
	ID-formation and a section of the section of the	
	-"Reference point - coordinate" (machine data 3) is greater than the positive software limit	The The
	switch	The state of the s
	SWILCH	*O,
	-Incorrect encoder actual value	(A)
	-incorrect encoder actual value	'
	Effect:	72/2
	The axis movement is stopped via the	12° 3
	deceleration ramp.	
A200	No position has been programmed in the NC	The axis number and the positional value must
	block for the roll feed version, although the	be specified in every NC block for the roll feed
No position has been	axis number of the roll feed is specified.	version.
programmed in	, Vg.,	Mar.
Automatic mode	Effect:	70x
	NC program execution is inhibited or aborted,	2. The state of th
	the axis is brought to a standstill via the	, S.
1001	deceleration ramp.	Ma 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A201	The decoded NC block needs a path or axis	When using linear interpolation with path
Naalaaitbaa be	velocity.	velocity (G01), a path velocity must be defined
No velocity has been	T#aati	with F. When using chaining with axis velocity
programmed in Automatic mode	Effect:	(G77), the axis velocities must be defined with
Automatic mode	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	FX, FY, etc. When using roll feed with axis velocity (G01), the velocity must be defined
	deceleration ramp.	with F.
	accordiation ramp.	with the second

Number / Alarm	Cause	Counter-measure
A202	An axis which does not exist was detected in	Correct the NC block.
	the decoded NC block. A logical name (X, Y,	727
Axis unknown	Z, A, B, C) must be assigned to each axis with	4
	machine data 2 (axis assignment). Only these	
	logical axis names can be used in the NC	9
	block. These errors cannot normally occur,	10.2
	since the logical axis names are verified when	2G/2
	the NC blocks are entered.	-Ci,0
		40,
	Exception: Machine data 2 (axis assignment)	(A)
	is changed afterwards.	
	T. NO. 3	72,
	The NC program number and NC block	20,
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values – decoder error location"	75,
	task.	The The
	C#oots	790)
	Effect:	'0L.
	NC program execution is inhibited or aborted,	The state of the s
	the axis is brought to a standstill via the	700
A202	deceleration ramp.	MDI mada Only COO (abaduta dimensions) or
A203	The NC block which was read in contains an	-MDI mode:Only G90 (absolute dimensions) or
1st G-function not	illegal 1st G function.	G91 (incremental dimensions) can be entered
	The NC program number and NC block	as the 1st G function. Only G91 is allowed for the roll feed version.
allowed	The NC program number and NC block	the roll feed version.
	number in which the NC block decoder	Automotic/cinale block mode. Define a legal
	detected the error can be read out with the "output actual values - decoder error location"	-Automatic/single-block mode:Define a legal 1st G function according to the table (see the
	task.	Programming Guide).
	lask.	Frogramming Guide).
	Effect:	(A)
	The axis movement is inhibited or stopped via	, (Q),
	the deceleration ramp.	-th,
A204	The NC block which was read in contains an	-MDI mode:Only G30 to G39 (acceleration
71204	illegal 2nd G function.	override) can be entered as the 2nd G
2nd G-function not	mogar zna o ranottori.	function.
allowed	The NC program number and NC block	Turiotion.
	number in which the NC block decoder	-Automatic/single-block mode:Define a legal
	detected the error can be read out with the	2nd G function according to the table (see the
	"output actual values - decoder error location"	Programming Guide).
	task.	The grant,
	70,0	700
	Effect:	450
	The axis movement is inhibited or stopped via	All and the second second
	the deceleration ramp.	7, 7
A205	The NC block which was read in contains an	-MDI mode:No 3rd G function is allowed.
	illegal 3rd G function.	
3rd G-function not	197 _A	-Automatic/single-block mode:Define a legal
allowed	The NC program number and NC block	3rd G function according to the table (see the
	number in which the NC block decoder	Programming Guide).
	detected the error can be read out with the	(0)
	"output actual values - decoder error location"	30,
	task.	, dV
	Mr. Mr.	M.
	Effect:	" " " " " " " " " " " " " " " " " " "
	The axis movement is inhibited or stopped via	4
	the deceleration ramp.	

Number / Alarm	Cause	Counter-measure
A206	The NC block which was read in contains an illegal 4th G function.	-MDI mode:No 4th G function is allowed.
4th G-function not allowed	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location"	-Automatic/single-block mode:Define a legal 4th G function according to the table (see the Programming Guide).
, w.i.glipatterno	task. Effect: The axis movement is inhibited or stopped via the deceleration ramp.	Jtornat.
A208 D-number is not	A D number greater than 20 was found in the decoded NC block.	Correct the NC block.
allowed	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location" task.	ACTE BY ACTE ACTE BY ACTE ACTE BY ACTE ACTE ACTE ACTE ACTE ACTE ACTE ACTE
WANTER THE	Effect: The axis movement is inhibited or stopped via the deceleration ramp.	The state of the s
A210 Interpolation of 3 axes	The decoded NC block contains an interpolation of 3 or more axes.	Correct the NC block. Only 2D interpolation is allowed.
not allowed	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location" task.	Toughor, Applichaphor,
Mary.	Effect: NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	Haray.
A211 Shortest distance G68	G function G68 (shortest path for rotary axis) was detected in the decoded NC block, although G91 (incremental dimensions) is	Correct the NC block.Function G68 can only be programmed in association with G90 (absolute dimensions).
and G91 not allowed	active.	(absolute differisions).
	Example: N10 G91 G68 X20.000	und de
\$1.	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location"	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
, and a second	task. Effect:	The state of the s
dparite	NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	it. Aprille

Number / Alarm	Cause	Counter-measure
A212	A different axis was programmed in the NC	Correct the NC program. The axis used in the
12 12	block following a special function (M7 only).	NC block with the special function must also
Consist function and	block following a special fullction (IVIT Offly).	
Special function and		be programmed in the next NC block.
xis combination not	Example:	
llowed	N10 G50 X100 F1000	
	N15 G90 Y200 incorrect	
	N15 G90 X200 correct	Mr.
	1113 G30 A200 Collect	7/2
		The Thirt
	The NC program number and NC block	XO. XO.
	number in which the NC block decoder	
	detected the error can be read out with the))
	"output actual values - decoder error location"	700
		The.
	task.	250
	Effect:	
	NC program execution is inhibited or aborted,	
		78,
	the axis is brought to a standstill via the	To. To.
	deceleration ramp.	70,
213	The decoded NC block contains several D	Correct the NC block.
×0/,	numbers.	55501 1110 110 5100111
Joseph D. Lander	numbers.	7, 2
ultiple D-number not	70,0	1000
owed	Example:	(Q)*
	N1 G41 D3 D5.	74.
	111 S F1 B0 B0.	"The
	- 110 Az	73
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	9
		79×
	"output actual values - decoder error location"	The The
	task.	79.)
	76.	The state of the s
	Effect:	\$50.
		²⁰
	NC program execution is inhibited or aborted,	.20°
	the axis is brought to a standstill via the	750
	deceleration ramp.	The same of the sa
214	The decoded NC block contains several	Correct the NC block.
214		Correct the INC block.
	mutually exclusive G functions from the	
Iultiple acceleration	acceleration override group (G30 to G39).	
ehaviour not allowed	98.	98,
	Example:	The Man
	N1 G34 G35	70,
	N1 G34 G33	The State of the S
	xO^*	xO'
	The NC program number and NC block	
	number in which the NC block decoder	34
	100	. (0)
	detected the error can be read out with the	$-a_{h}$.
	"output actual values - decoder error location"	72,
	task.	1.
	Γ#oot:	
	Effect:	9, 9,
	NC program execution is inhibited or aborted,	70%
	the axis is brought to a standstill via the	id id
	deceleration ramp.	VD.,
215	The decoded NC block contains several	Correct the NC block.
210		Correct the INC block.
	mutually exclusive G functions from the	7.0°
lultiple special	special function group (G87, G88, G89, G50,	(0)
inctions not allowed	G51).	
		24,
	Francis 33	-24
	Example:	
	N1 G88 G50	
	9	9
	The NC program number and NC block	79×
		"The
	number in which the NC block decoder	79.)
	detected the error can be read out with the	off.
	"output actual values - decoder error location"	\$6.
	task.	1°
	iuon.	.70"
	359	7.50
	Effect:	724
	NC program execution is inhibited or aborted,	$\mathcal{H}_{A_{a}}$
	the axis is brought to a standstill via the	76
	deceleration ramp.	

Number / Alarm	Cause	Counter-measure
A216	The decoded NC block contains several	Correct the NC block.
Multiple block transition	mutually exclusive G functions from the block transition group (G60, G64, G66, G67).	Way.
not allowed	Evample:	
	Example: N1 G64 G66 X1.000 FX100.00	7/0 tj
	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the	JUNE TO THE THE PERSON OF THE
	"output actual values - decoder error location" task.	,HIdb.
	24,	127
	Effect:	
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	, d
A217	The decoded NC block contains the same axis more than once.	Correct the NC block.
Multiple axis	more than ones.	10,
programming not allowed	Example: N1 G90 G01 X100.000 X200.000 F100.00	
	The NO seed seed to see the seed NO block	The state of the s
24	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the	3,
9	"output actual values - decoder error location"	6
y" .20	task.	29ho.,
The same	Effect:	The state of the s
IIIO.	NC program execution is inhibited or aborted,	20,
.700	the axis is brought to a standstill via the	, 120°
A040	deceleration ramp.	Compat the NC block
A218 Multiple path condition	The decoded NC block contains several mutually exclusive G functions from the preparatory function group	Correct the NC block.
not allowed	(G00/G01/G76/G77).	9 9
	Example:	10 x
	N1 G01 (linear interpolation) G77 (chaining) X10 F100.	ROTTATES
1920	The NC program number and NC block	
new.	number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location"	May.
	task.	
g)	Effect	9
	Effect: NC program execution is inhibited or aborted,	Tho.
-Olligi	the axis is brought to a standstill via the deceleration ramp.	"Olligit" Olligit
A219	The decoded NC block contains several	Correct the NC block.
Multiple dimensions	mutually exclusive G functions from the dimensional notation group (G90/G91).	MHI ID
specification not allowed	Example:	20,
<u> </u>	N1 G90 G91.	2 2
	The NC program number and NC block	79%
	number in which the NC block decoder	765
-4/1/2	detected the error can be read out with the	"Ollis" Ollis
Salite.	"output actual values - decoder error location" task.	The Kaliffe
		7/0,
ala.	Effect:	$n_{I_{I_{I_{I_{I_{I_{I_{I_{I_{I_{I_{I_{I_$
2,	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	7,
	deceleration ramp.	
A)		- A

Number / Alarm	Cause	Counter-measure
A220	The decoded NC block contains several	Correct the NC block.
	mutually exclusive G functions from the zero	100 m
Multiple zero offset	offset group (G53 to G59).	7, 7
selection not allowed		
	Example:	9
×	N1 G54 G58	70×
2	Tb: 70	161. 161.
- C	The NC program number and NC block	Lo.
XOV.	number in which the NC block decoder	10°
~80	detected the error can be read out with the	
(6)	"output actual values - decoder error location"	(6)
12%	task.	$A_{f_{f_{i}}}$
72,	The state of	All the second s
	Effect:	
	NC program execution is inhibited or aborted,	
9	the axis is brought to a standstill via the	9, 9,
, · · ·	deceleration ramp.	10°
A221	The decoded NC block contains several	Correct the NC block.
-C'6	mutually exclusive G functions from the tool	alle alle
Multiple tool offset	offset selection group (G43/G44).	10.
selection not allowed	1000	80°
(4)	Example:	(40)
72,	N1 G43 G44 D2	744
20,	20, 20,	70,0
	The NC program number and NC block	
	number in which the NC block decoder	
<i>Q</i> ,	detected the error can be read out with the	3,
	"output actual values - decoder error location"	Mo.
, ć	task.	190
ALC:	Section 2	Office Office
	Effect:	
700	NC program execution is inhibited or aborted,	\$\dot{\dot{\dot{\dot{\dot{\dot{\dot{
775	the axis is brought to a standstill via the	7/5
21/2	deceleration ramp.	- 11 m
A223	The decoded NC block contains a subprogram	Correct the NC block.
	call, however the NC program which was	
Subprogram number	called does not exist in the memory of the	
does not exist	technology.	. 25
,	The state of the s	The state of the s
- A	Effect:	My,
*0//	NC program execution is inhibited or aborted,	x0 ¹
200	the axis is brought to a standstill via the	
.201	deceleration ramp.	.20
A224	The permissible nesting depth of subprograms	Correct the NC program.
Th.	was exceeded. Recursive calling of	347
Subprogram nesting	subprograms.	The permissible nesting depth for
depth not allowed		subprograms is 2 subprogram levels.
2	The NC program number and NC block	9
120	number in which the NC block decoder	79×
2	detected the error can be read out with the	7/bs 7/bs
No.	"output actual values - decoder error location"	40
10)	task.	10,
792	~90°	S. Carrier
(2)	Effect:	
947	NC program execution is inhibited or aborted,	147
The same of the sa	the axis is brought to a standstill via the	70° .
-	deceleration ramp.	

Number / Alarm	Cause	Counter-measure
A225	The decoded NC block contains simultaneous	Correct the NC block.
- 2 ₁ ,	selection and deselection of collision	The state of the s
Status of collision	monitoring (G96/G97).	
monitoring select. not	5 N4 000 007 V400	
allowed	Example: N1 G96 G97 X100	0
	The NC program number and NC block	F3.,
	The NC program number and NC block number in which the NC block decoder	30,
	detected the error can be read out with the	Office Office
	"output actual values - decoder error location"	716 July 1
	task.	, ×200
	tuon.	2,6
	Effect:	- Gilly
	NC program execution is inhibited or aborted,	1,
	the axis is brought to a standstill via the	
	deceleration ramp.	9
A227	The look-ahead function of the decoder has	Correct the NC program.
	detected that the negative software limit switch	Check the machine data.
Negative overtravel	will be crossed. See also error message	The state of the s
violated	"A195: Negative overtravel reached".	40.
	2007	, x ₀ 2,
	The NC program number and NC block	770
	number in which the NC block decoder	Fig.
	detected the error can be read out with the	27,
	"output actual values - decoder error location"	
	task.	
	£4	197
	Effect:	All
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	The state of the s
	deceleration ramp.	*O,
A228	The look-ahead function of the decoder has	Correct the NC program.
AZZO	detected that the positive software limit switch	Check the machine data.
Positive overtravel	will be crossed. See also error message	Oneok the machine data.
violated	"A196: Positive overtravel reached".	My.
	7110011 COMMO CYCHIAYOTTCACHOA	
	The NC program number and NC block	
	number in which the NC block decoder	"S, "S,
	detected the error can be read out with the	"He
	"output actual values - decoder error location"	Typ.
	task.	*0°
	200	22.
	Effect:	190
	NC program execution is inhibited or aborted,	947
	the axis is brought to a standstill via the	227
1044	deceleration ramp.	1 10 11
A241	The table assignment has been changed from	Load the table again.
Table assistant	1 table to 2 tables or vice-versa.	Nata of
Table assignment	T#oots	Note:
changed	Effect:	A table can only be loaded again if it is not
	NC tables cannot be processed.	selected. The warning is cleared automatically when the table has been successfully loaded.
A242	Table 1 was not loaded correctly or has been	Load table 1 again.
N272	reset.	Load table I again.
Table 1 invalid	1000	Note:
Table I IIIvalla	Effect:	Table 1 can only be loaded again if it is not
	Table 1 cannot be processed.	selected. The warning is cleared automatically
	. a.s. o rodiniot do prodocod.	when table 1 has been successfully loaded.
A243	Table 2 was not loaded correctly or has been	Load table 2 again.
	reset.	about again.
	10.000	14
Table 2 invalid	37	Note:
Table 2 invalid	Effect:	Note: Table 2 can only be loaded again if it is not
Table 2 invalid	Effect: Table 2 cannot be processed.	Note: Table 2 can only be loaded again if it is not selected. The warning is cleared automatically

Table 12-2 Alarm numbers, causes and their counter-measures

12.3 Fatal errors (FF)

Fatal errors are serious hardware or software errors which no longer permit normal operation of the unit. They only appear on the PMU in the form "FF<No>". The software is re-booted by actuating any key on the PMU.

Number / Fault	Cause	Counter-measure
FF01 Time slot overflow	A time slot overflow which cannot be remedied has been detected in the high-priority time slots.	- Reduce pulse frequency (P340) - Replace CU
FF04 RAM	A fault has occurred during the test of the RAM.	Replace CU
FF05 EPROM fault	A fault has occurred during the test of the EPROM.	Replace CU
FF13 Wrong firmware version	A version conflict between the firmware and the hardware has occurred.	- Replace firmware - Replace CU

Table 12-3 Fatal errors

10.98 Environmental Friendliness

13 Environmental Friendliness

Environmental aspects during the development

The number of components has been significantly reduced over earlier converter series by the use of highly integrated components and the modular design of the complete series. Thus, the energy requirement during production has been reduced.

Special significance was placed on the reduction of the volume, weight and variety of metal and plastic components.

Plastics components used

ABS: PMU board, Siemens logo PC / ABS: Front cover MC Large

PA6: Front cover MC, terminal strips,

spacer bolts, fan impeller

PA6.6: DC link terminal cover,

through terminals, terminal strips, terminal

blocks

PVC: Optional card covers

PP: PMU covers
PBTP: Fan housing
PC (Makrolon): Fan guides
HP2061 (Phenolharz): Insulating plates
NOMEX: Insulating paper

Halogen-containing flame retardants were, for all essential components, replaced by environmentally-friendly flame retardants. Environmental compatibility was an important criterium when selecting the supplied components.

Environmental aspects during production

Purchased components are generally supplied in recyclable packaging materials (board).

Surface finishes and coatings were eliminated with the exception of the galvanized sheet steel side panels.

ASIC devices and SMD devices were used on the boards.

The production is emission-free.

Environmental aspects for disposal

The unit can be broken down into recyclable mechanical components as a result of easily releasable screw and snap connections.

The plastic components are to DIN 54840 and have a recycling symbol.

Units can be disposed of through certified disposal companies. Addresses are available from your local Siemens partner.

10.98 Certificates

14 Certificates

SIEMENS

Automation and Drives

Confirmation

Erlangen, 15.09.1998

This confirms that

Equipment

drive converter

Type

SIMOVERT MASTERDRIVES

• Order No.

6SE70xx-xxPxx 1)

is manufactured in conformance with EN 60204 Section 6.2 (corresponds to DIN VDE 0113 Section 6.2).

1) See rating plate for complete type designation, serial number and technical data

This equipment fulfills the protection requirements against electrick shock according to DIN VDE 0106 Part 100 when the following safety rules are observed:

- Service work in operation is only permissible on a unit which is not live.
- The converter must be switched into a no-voltage condition and isolated from the supply when replacing any part/component.
- All panels and the DC link terminals must be closed during operation.

Thus, this equipment conforms to the appropriate regulations in Germany according to VBG 4 §2 (2) (VBG is a German regulatory body for safety-related issues).

The local operating regulations (e.g. EN 50110-1, EN 50110-2) must be observed when operating the equipment.

A&D DS A P1

Mickal

Certificates 10.98

SIEMENS

Automation and Drives

Test Certificate

Erlangen, 15.09.1998

Equipment

Type

drive converter

SIMOVERT MASTERDRIVES

• Order No.

6SE70xx-xxPxx 1)

The 100% inspection was performed according to test instructions Motion Control 6SE70xx-xxPxx.

Test scope:

- Protective conductor test
- II. Insulation test
- III. Function test acc. to EN 50178
- According to DIN VDE 0411
- Acc. to EN 50178, Section 9.4.5.2 and UL508/CSA 22.2-14.M 91, Section 6.8
- Initialization and start-up
- Customer terminals test
- Power section inspection
- Inspection of protection and monitoring devices
- IV. RUN-IN
- V. Function test acc. to EN 50178
- Continuous test > 5 hours ambient temperature 55 °C
- see III. Function test

The equipment complied with the test requirements.

The test results are documented within the test data base.

1) See rating plate for complete type designation, serial number and technical data

A&D DS A PE D P

Moger

Schlögel

Automation & Drives

10.98 Certificates

SIEMENS

Factory certificate

regarding electromagnetic compatibility

EMC 0998 / Motion Control

Manufacturer: Siemens Aktiengesellschaft

Group Automation and Drives
Business Division Variable-speed drives
Sub-Division AC drive systems

Address: P.O. Box 3269

D-91050 Erlangen

Product name: SIMOVERT

Type 6SE70xx-xxPxx 13

When correctly used, the designated product fulfills all the requirements of Directive 89/336/EEC regarding electromagnetic compatibility.

We confirm the conformance of the above designated product with the Standards:

EN 61800-3 10-1996

EN 61000-4-2 (old IEC 801-2)

EN 61000-4-4 (old IEC 801-4)

EN 61000-4-5 (old IEC 801-5)

IEC 1000-4-3 (old IEC 801-3)

Note:

These instructions relating to EMC-correct installation, correct operation, connecting-up conditions and associated instructions in the product documentation supplied must be observed.

1) See rating plate for complete type designation, serial number and technical data

Erlangen, 15.09.1998

H. Mickal A&D DS A P1

*) Acc. to EN 10204 (DIN 50049)

Automation

This declaration does not guarantee any features

Mulus 2

A&S DS 4102x

Copyright (©) SIEMENS AG 1997 All rights reserved

Page 1 of 1

Bisher sind folgende Ausgaben erschienen:

Ç	Ausgabe	Interne Sachnummer
	AA	475 901 4170 76 J AA-74
	AB	475 901 4170 76 J AB-74
	AC	475 901 4170 76 J AC-74

Ausgabe AC besteht aus folgenden Kapiteln:

Kapitel		Änderungen	Seitenzahl	Ausgabedatum
100	Definitionen und Warnungen	überarbeitete Ausgabe	4 (6)	10.98
2	Beschreibung	überarbeitete Ausgabe	100	10.98
3	Erstinbetriebsetzung	überarbeitete Ausgabe	2	10.98
4	Transportieren, Lagern, Auspacken	überarbeitete Ausgabe	1	10.98
5	Montage	überarbeitete Ausgabe	8	<u></u> 10.98
6	EMV-gerechter Aufbau	überarbeitete Ausgabe	2	10.98
7000	Anschließen	überarbeitete Ausgabe	11 , 5	10.98
8	Parametrierung	überarbeitete Ausgabe	27	10.98
9	Wartung	überarbeitete Ausgabe	3	10.98
10	Formieren	überarbeitete Ausgabe	2	10.98
11	Technische Daten	überarbeitete Ausgabe	7	10.98
12	Störungen und Warnungen	überarbeitete Ausgabe	33	10.98
13	Umweltverträglichkeit	überarbeitete Ausgabe	1 3	10.98
14	Bescheinigungen	überarbeitete Ausgabe	3	10.98

The following editions have been published so far:

Edition	Internal Item Number
AA	475 901 4170 76 J AA-74
AB	475 901 4170 76 J AB-74
AC	475 901 4170 76 J AC-74

Version AC consists of the following chapters:

Chapter		Changes	Pages	Version date
1	Definitions and warnings	reviewed edition	4	10.98
2	Description	reviewed edition	1	10.98
3	First Start-up	reviewed edition	2	10.98
4	Transport, Storage, Unpacking	reviewed edition	1000	10.98
5	Installation	reviewed edition	8	10.98
6	Installation in Conformance with EMC Regulations	reviewed edition	2	10.98
7	Connecting-up	reviewed edition	11	10.98
8	Parameterization	reviewed edition	27	10.98
9 🔏	Maintenance	reviewed edition	3 <	10.98
10	Forming	reviewed edition	2	10.98
11	Technical Data	reviewed edition	7	10.98
12	Faults and Warnings	reviewed edition	31	10.98
13	Environmental friendliness	reviewed edition	1	10.98
14	Certificates	reviewed edition	3	10.98

Group: Automation and Drives (A&D) Division: Variable-Speed Drive Systems Postfach 3269, D-91050 Erlangen